


Date: October 30, 2012  
File #: 09 - 312701  
Folder Name: 606 MARYLAND AVE E  
PIN: 292922120095



goes through intervening space, (kitchen)  
door under 6' - therefore, can't be  
counted as a 2nd exit

door under to  
open through interior space (interior)

