


161 & 163 Acker St.





The City of Saint Paul Reporting of Bypass - Unauthorized Discharges

Time and Date of Discovery: 9:00 AM x PM **Date** 7/8/13

Location of Bypass/Discharge: south curb line in front of 160 Acker

Cause of Bypass/Discharge: Failed private shared sewer service to 161 and 163 West Acker St.

Length of Time Bypass/Discharge: Unknown

Quantity of Flow Bypassed/Discharged: Unknown

Name of Receiving Water or System: None, spill contained to street

Description of City Actions being taken to abate or control the bypass/unauthorized discharge.

Update to Spill Report 135047 filed on Wednesday, July 3. On 07/08/13 at 9:00 am, it was discovered that the property owners had turned on their water services and sewer spill was occurring again. Sewer Maintenance cleaned and vacted the street. Water Department physically disconnected water services to 161 and 163 Acker. Spill is now stopped.

Paula Seeley, Department of Safety and Inspection at 651-266-1916 is working with property owners to repair private sewer service.

Person making notification to Minnesota Pollution Control Agency (MPCA)

Shawn O'Keefe

Name of MPCA Staff Notified: Laurie Duty Officer #33, Report Number 135125

Date and Time MPCA Staff Notified: 10:00 AM X PM **Date:** 07/08 2013



Name of City Staff Notified: Bruce Elder

*** Mail Completed Form To:**
Chandi McCracken, Water Quality Compliance
Minnesota Pollution Control Agency
520 Lafayette Road
St. Paul, Minnesota 55155

Send Copy of Form To:
Bruce Elder, Assistant City Engineer
Sewer Utility
700 City Hall Annex
25 W 4th Street
St. Paul, Minnesota 55102

Note: Bypass/Discharge Includes Sanitary Sewage, Stormwater and Clearwater.

cc: Rich Lallier, Director of Public Works



ACKER 2 ST. N

sewer print