

OtherOther

APPLICATION FOR APPEAL

RECEIVED
SEP 2 8 2010
CITY CLERK

Saint Paul City Clerk

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8560

The City Clerk needs the following to process your app \$25 filing fee payable to the City of Saint Paul (if cash: receipt number) Copy of the City-issued orders or letter which are being appealed Attachments you may wish to include This appeal form completed	YOUR HEARING Date and Time: Tuesday, Oct 5 Time 1:30 Location of Hearing: Room 330 City Hall/Courthouse
Address Being Appealed:	
Number & Street: 2000 Ivy aue E	
	Email mbmurphy & cloburnet
Phone Numbers: Business Residen	ce Cell 651-399-7124
Signature: Non My	
Name of Owner (if other than Appellant):	
Address (if not Appellant's): 4378 Livings	stor Dr.
Phone Numbers: Business Residen	ce Cell
What Is Being appealed and w	hy? Attachments Are Acceptable
Vacate Order/Condemnation/ Revocation of Fire C of O	
Summary/Vehicle Abatement	
□ Fire C of O Deficiency List	
Fire C of O: Only Egress Windows	
Code Enforcement Correction Notice	
□ Vacant Building Registration	
□ Other	

Fire Inspection Division Bob Kessler, Director

CITY OF SAINT PAUL Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806 Telephone: 651-266-8989 Facsimile: 651-266-8951

Hacsimue: 031-200-8931 Web: <u>www.stpaul.gov/dsi</u>

September 15, 2010

MICHAEL BRIAN MURPHY SHARON G MURPHY 4378 LIVINGSTON DR. EAGAN MN 55123-2604

FIRE INSPECTION CORRECTION NOTICE

RE:

2000 IVY AVE E

Ref. #100697

Residential Class: C

Dear Property Representative:

Your building was inspected on September 15, 2010 for the renewal of your Fire Certificate of Occupancy. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected prior to the re-inspection date. A reinspection will be made on October 15, 2010 at 9:30 A.M..

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

YOU WILL BE RESPONSIBLE FOR NOTIFYING TENANTS IF ANY OF THE FOLLOWING LIST OF DEFICIENCIES ARE THEIR RESPONSIBILITY.

DEFICIENCY LIST

- 1. Attic SPLC 34.10 (4), 34.33 (3) Provide a bathroom floor impervious to water. Caulk the base of the toilet.
- 2. Attic MN Stat 299F.18 Immediately remove and discontinue excessive accumulation of combustible materials.-Remove all sheet rock from the hallway in attic.
- 3. Attic SPLC 34.10 (7), 34.33 (6) Repair or replace and maintain the woodwork in an approved manner.-Closet doors Bedroom south side

- 4. Attic MSFC1026.1 Provide and maintain an approved escape window from each sleeping room. The minimum size must be 5 square feet of glazed area with a minimum of 24 inches of openable height and 20 inches of openable width. With a finished sill height not more than 48 inches. This work may require permit(s). Call DSI at (651)-266-9090. Refer to the Escape Windows for Residential Occupancies handout for more information.-Windows in attic measure the same in both bedrooms. Openable height is 20inches and the openable width is 31inches. The Glazed area is 38inches height by 27inches width with a Sill of 34inches.
- 5. Basement MSFC 605.5 Discontinue use of extension cords used in lieu of permanent wiring.-TV Room behind TV
- 6. Exterior Eastside and North Side of House MSFC 605.1- All light fixtures shall be maintained with protective globes if originally equipped.
- 7. GARAGE SPLC 34.08 (5), 34.31 (3) Repair, replace and maintain all exterior surfaces on fences, sheds, GARAGE and other accessory structures free from HOLES and deterioration. Provide and maintain exterior unprotected surfaces PAINTED or protected from the elements.
- 8. HOUSE SPLC 34.09 (1) b,c, 34.32 (1) b,c Provide and maintain all exterior walls free from holes and deterioration. ALL WOOD exterior unprotected surfaces must be painted or protected from the elements and maintained in a professional manner free from chipped or peeling paint.
- 9. Main Floor MSFC 605.4 Discontinue use of all multi-plug adapters.-Living room and Kitchen
- 10. Main Floor SPLC 34.10 (4), 34.33 (3) Provide a bathroom floor impervious to water. Caulk the base of the toilet.
- 11. Main Floor SPLC 34.10 (7), 34.33 (6) Repair and maintain the walls in an approved manner.-Repair or replace the damaged or deteriorated wall coverings. Wall tile has fallen off replace.
- Main Floor North Side MSFC1026.1 Provide and maintain an approved escape window from each sleeping room. The minimum size must be 5 square feet of glazed area with a minimum of 24 inches of openable height and 20 inches of openable width. With a finished sill height not more than 48 inches. This work may require permit(s). Call DSI at (651)- 266-9090. Refer to the Escape Windows for Residential Occupancies handout for more information.-Bedroom North side main floor is 23 inches openable height and 39 inches openable width with a Sill of 27 inches Glazed area is 46 inches height by 36 inches width
- Main Floor South Side MSFC1026.1 Provide and maintain an approved escape window from each sleeping room. The minimum size must be 5 square feet of glazed area with a minimum of 24 inches of openable height and 20 inches of openable width. With a finished sill height not more than 48 inches. This work may require permit(s). Call DSI at (651)- 266-9090. Refer to the Escape Windows for Residential Occupancies

handout for more information.-Bedroom windows main floor south side are 20 inches openable height and openable width is 35 inches with a Sill of 36 inches and the Glazed area is 38 inches height by 32 inches width.

- 14. SPLC 34.11 (6), 34.34 (3) Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.
- 15. UMC 504.6 Provide, repair or replace the dryer exhaust duct. Exhaust ducts for domestic clothes dryers shall be constructed of metal and shall have a smooth interior finish. The exhaust duct shall be a minimum nominal size of four inches (102 mm) in diameter. This work WILL require a permit(s). Call DSI at (651) 266-8989.-Exhaust duct installed without permit.
- 16. MMC SEC 103 Mechanical systems both existing and new and parts of those systems shall be maintained in proper operating conditions in accordance with the original design and in a safe and sanitary condition. Remove all lint and dust from behind the dryer.

For an explanation or information on some of the violations contained in this report, please visit our web page at: http://www.ci.stpaul.mn.us/index.aspx?NID=211

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8688) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: james.thomas@ci.stpaul.mn.us or call me at 651-266-8983 between 7:30 a.m. - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

James Thomas Fire Inspector

Reference Number 100697