

**From:** [Moermond, Marcia \(CI-StPaul\)](#)  
**To:** [Zimny, Joanna \(CI-StPaul\)](#); [Vang, Mai \(CI-StPaul\)](#)  
**Subject:** FW: 680/690 Bayfield  
**Date:** Sunday, January 9, 2022 4:24:35 PM  
**Attachments:** [image001.png](#)  
[image002.png](#)  
[image003.png](#)  
[image004.png](#)

---

Mai/Joanna, Please attach to record. I also think there were some documents submitted by the owner which have yet to be attached. Thank you! -Marcia

---

**From:** Ubl, Stephen (CI-StPaul) <[stephen.ubl@ci.stpaul.mn.us](mailto:stephen.ubl@ci.stpaul.mn.us)>  
**Sent:** Friday, January 7, 2022 4:33 PM  
**To:** Moermond, Marcia (CI-StPaul) <[marcia.moermond@ci.stpaul.mn.us](mailto:marcia.moermond@ci.stpaul.mn.us)>  
**Cc:** Imbertson, Mitchell (CI-StPaul) <[mitchell.imbertson@ci.stpaul.mn.us](mailto:mitchell.imbertson@ci.stpaul.mn.us)>  
**Subject:** 680/690 Bayfield

Hi Marcia,

I spoke with Fire Inspector Mitch Imbertson, regarding the areas I the hangers that are not protected with the sprinkler system. Because of the tight, confined spaces, it's not realistic to get up there and complete deficiencies that we encountered. Mitch and I agree that the owner should patch the holes where possible and we would accept the remaining conditions as they are. Mitch could offer a more detailed explanation of the patchwork if the owner has any questions.

Thank you,



**SAINT PAUL**  
**MINNESOTA**

Stephen Ubl  
Pronouns: He/Him/His  
Building Official  
Department of Safety and Inspections  
375 Jackson St.  
Saint Paul, MN 55101  
P: 651-266-9021  
Email: [Stephen.ubl@ci.stpaul.mn.us](mailto:Stephen.ubl@ci.stpaul.mn.us)

