

Date: June 27, 2011
File #: 10 - 900356
Folder Name: 611 MARYLAND AVE E
PIN: 202922430087



Rear Strivell light -
top of stairway
light does not shine around
corner of stairwell / hallway to
near 1st floor unit entry door

look

Date: June 27, 2011
File #: 10 - 900356
Folder Name: 611 MARYLAND AVE E
PIN: 202922430087



*2nd floor front entry
top of stairs - no light fixture*

Date: June 27, 2011
File #: 10 - 900356
Folder Name: 611 MARYLAND AVE E
PIN: 202922430087



Date: June 27, 2011
File #: 10 - 900356
Folder Name: 611 MARYLAND AVE E
PIN: 202922430087



Light on 1st floor ceiling of
front entry
Stairway turns right - no light
top of stairs - light does not
shine around corner to unit
doorway

Date: June 27, 2011
File #: 10 - 900356
Folder Name: 611 MARYLAND AVE E
PIN: 202922430087

O. Ayler



*front hallway / hallway
1st floor*