

□ Other

# **APPLICATION FOR APPEAL**

RECEIVED

OCT 1 3 2010

CITY CLERK

## Saint Paul City Clerk

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8560

ocess your appeal: aint Paul er which	YOUR HEARING Date and Time:  Tuesday, Oct. 210  Time
ed:	
	T. Paul State: Mn Zip: 55/05
16NVSON E1	mail <u>ACAE @Wede Magnuson</u>
Residence	Cell 612-790-5542
	Date: 13010
FRID SCH	MDT
NE	· · · · · · · · · · · · · · · · · · ·
Residence	Cell 651-402-3996
What Is Being appealed and why? Attachments Are Acceptable	
20 100 -11	BRooms that & Mul Short niches - House is in levine storic des mut - 120+1 pears
	aint Paul er which e  ed: City: Residence Residence Residence d and why?



CITY OF SAINT PAUL Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806 

 Telephone:
 651-266-8989

 Facsimile:
 651-266-8951

 Web:
 www.stpaul.gov/dsi

October 4, 2010

FREDRICK SCHMIDT 1855 SUMMIT AVE ST PAUL MN 55105

### FIRE INSPECTION CORRECTION NOTICE

RE:

302 RYAN AVE

Ref. #106813

Residential Class: C

### Dear Property Representative:

Your building was inspected on October 4, 2010 for the renewal of your Fire Certificate of Occupancy. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected prior to the re-inspection date.

#### A re-inspection will be made on November 5, 2010 at 1:30 PM.

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

YOU WILL BE RESPONSIBLE FOR NOTIFYING TENANTS IF ANY OF THE FOLLOWING LIST OF DEFICIENCIES ARE THEIR RESPONSIBILITY.

#### **DEFICIENCY LIST**

- 1. 1st Floor Kitchen SPLC 34.10 (7), 34.33 (6) Repair and maintain the ceiling in an approved manner.
- 2. 1st Floor Living room MSFC 605.5 Discontinue use of extension cords used in lieu of permanent wiring.
- 3. 1st Floor Living room SPLC 34.14 (2), 34.34 (5) Provide an approved electrical service adequate to meet the buildings needs. This work may require a permit(s), call DSI at (651) 266-9090.-Remove 3 prong adapter from outlet.

An Equal Opportunity Employer

- 4. 1st Floor North bedroom SPLC 34.09 (3), 34.32 (3) Repair and maintain the window in good condition.-Window does not stay open.
- 5. 1st Floor South bedroom SPLC 34.09 (3), 34.32 (3) Repair and maintain the window in good condition.-Window does not stay open.
- 6. 1st Floor South bedroom MSFC1026.1 Provide and maintain an approved escape window from each sleeping room. The minimum size must be 5 square feet of glazed area with a minimum of 24 inches of openable height and 20 inches of openable width. With a finished sill height not more than 48 inches. This work may require permit(s). Call DSI at (651)- 266-9090. Refer to the Escape Windows for Residential Occupanices handout for more information.-Window measurements Height 20 in, Width 26 in.
- 7. 1st Floor MN State Statute 299F.50 Immediately provide and maintain an approved Carbon Monoxide Alarm in a location within ten (10) feet of each sleeping area. Installation shall be in accordance with manufacturers instructions.-Move Co detector from closet to hallway between bedrooms.
- 8. 2nd Floor MN State Statute 299F.50 Immediately provide and maintain an approved Carbon Monoxide Alarm in a location within ten (10) feet of each sleeping area. Installation shall be in accordance with manufacturers instructions.
- 9. 2nd Floor MSFC1026.1 Provide and maintain an approved escape window from each sleeping room. The minimum size must be 5 square feet of glazed area with a minimum of 24 inches of openable height and 20 inches of openable width. With a finished sill height not more than 48 inches. This work may require permit(s). Call DSI at (651)- 266-9090. Refer to the Escape Windows for Residential Occupanices handout for more information.-Window measurements are Height 18 1/2 in, Width 27 in.
- 10. 2nd Floor SPLC 34.09 (2), 34.32(2) Repair or replace the unsafe stairways, porch, decks or railings in an approved manner. This work may require a permit(s). Call DSI at (651) 266-9090.-Replace decayed flooring on deck.
- 11. 2nd Floor SPLC 34.09 (3), 34.32 (3) Repair and maintain the door frame.-Entry door.
- 12. SPLC 34.11 (6), 34.34 (3) Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.
- 13. SPLC 39.02(c) Complete and sign the provided smoke detector affidavit and return it to this office.

For an explanation or information on some of the violations contained in this report, please visit our web page at: http://www.ci.stpaul.mn.us/index.aspx?NID=211

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8688) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: mike.cassidy@ci.stpaul.mn.us or call me at 651-266-8984 between 7:30 a.m. - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Mike Cassidy Fire Inspector

Reference Number 106813