

The City Clerk needs the following to process Voltrappeds

\$25 filing fee payable to the City of Saint Paul

APPLICATION FOR APPEAL

Saint Paul City Clerk

RECEIVED
SEP 0 7 2011

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8560

(if cash: receipt number)	YOUR HEARING Date and Time:
Copy of the City-issued orders or letter which	6 2
are being appealed	Tuesday, <u>9-20-11</u>
Attachments you may wish to include This appeal form completed.	m 1'27
☐ This appeal form completed	Time
□ Walk-In OR □ Mail-In	Location of Hearing: Room 330 City Hall/Courthouse
	Room 550 City Hutt/Courthouse
Address Being Appealed:	
Number & Street: 767 /40///	City: St. Paul State: My Zip: 55104
Appellant/Applicant: John Erickson	Email 10 wood yerickson(a)
Phone Numbers: Business Residence	· · · · · · · · · · · · · · · · · · ·
Signature: Jo Can Cuckson	Date: Sept 7-2011
Name of Owner (if other than Appellant): John + R	chard Erickson
Address (if not Appellant's): 21 Arundel - 3	St. Paul, My 55102
Phone Numbers: Business Residence _	Cell
What Is Being Appealed and Wl	ny? Attachments Are Acceptable
Vacate Order/Condemnation/ Revocation of Fire C of O	
□ Summary/Vehicle Abatement	
□ Fire C of O Deficiency List	
Fire C of O: Only Egress Windows	
Code Enforcement Correction Notice	
□ Vacant Building Registration	
□ Other	



CITY OF SAINT PAUL Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806

 Telephone:
 651-266-8989

 Facsimile:
 651-266-8951

 Web:
 www.stpaul.gov/dsi

August 30, 2011

JOANN C ERICKSON RICHARD C ERICKSON 21 ARUNDEL AVE ST PAUL MN 55102-2201

FIRE INSPECTION CORRECTION NOTICE

RE:

767 HOLLY AVE Residential Class: C

Dear Property Representative:

Your building was inspected on August 30, 2011 for the renewal of your Fire Certificate of Occupancy. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected prior to the re-inspection date. A reinspection will be made on October 4, 2011 at 11:30 AM.

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

YOU WILL BE RESPONSIBLE FOR NOTIFYING TENANTS IF ANY OF THE FOLLOWING LIST OF DEFICIENCIES ARE THEIR RESPONSIBILITY.



Garage - MSFC 605.5 - Discontinue use of extension cords used in lieu of permanent wiring.

Second floor balcony - North side of house - SPLC 34.09 (2) 34.32 (2) - Provide an approved guardrail with intermediate ballustrade or rails 4 inches or less apart. This work may require a permit(s). Call DSI at (651) 266-9090.-Current guardrail is 33 inches high.

3. Upper level - MSFC 605.5.3 - Immediately, discontinue use of frayed, deteriorated, damaged or spliced electrical cords.-Discontinue use of temporary decorative lighting.

SPLC 34.11 (6), 34.34 (3) - Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.

- 5. SPLC 39.02(c) Complete and sign the provided smoke detector affidavit and return it to this office.
- 6. MSFC1026.1 Provide and maintain an approved escape window from each sleeping room. The minimum size must be 5 square feet of glazed area with a minimum of 24 inches of openable height and 20 inches of openable width. With a finished sill height not more than 48 inches. This work may require permit(s). Call DSI at (651)- 266-9090. Refer to the Escape Windows for Residential Occupancies handout for more information.-

Lower level north
18.25 h x 26.5 w Glazed 7.7 sq ft
Lower level south
21.5 h x 26.5 w Glazed 7.7 sq ft
Upper level south
16 h x 26.5 w Glazed 7.7 sq ft
Upper level north
23 h x 26.5 w Glazed 7.7 sq ft

What have the second of the se

7. SPLC 34.09 (3), 34.32 (3) - Repair and maintain the door in good condition.-Repair door and lock so door is easily openable.



UMC 504.6 - Provide, repair or replace the dryer exhaust duct. Exhaust ducts for domestic clothes dryers shall be constructed of metal and shall have a smooth interior finish. The exhaust duct shall be a minimum nominal size of four inches (102 mm) in diameter. This work requires a permit(s). Call DSI at (651) 266-8989.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8688) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: rick.gavin@ci.stpaul.mn.us or call me at 651-266-8994 between 7:30 a.m. - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Rick Gavin Fire Inspector

Reference Number 107378