




vinyl filler was used to fill in the hole & the window is not to be moved





hole caused by storm!