

The City Clerk needs the following to process your appeal:

\$25 filing fee payable to the City of Saint Paul

APPLICATION FOR APPEAL

RECEIVED

NOV 9 2011

CITY CLERK

Saint Paul City Clerk

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8560

(if cash: receipt number) Copy of the City-issued orders or letter which are being appealed Attachments you may wish to include This appeal form completed	YOUR HEARING Date and Time: Tuesday, 11-32-1 Time / 30 Location of Hearing:
Walk-In OR □ Mail-In	Room 330 City Hall/Courthouse
Address Being Appealed:	
Number & Street: 144 LEXINGTON PKWY N. City: ST. PAUL State: MN Zip: 55104 Appellant/Applicant: TODD FUNKE Email LGPROPG COMCAST. NET	
Signature: Todaf Jan	Date:
Name of Owner (if other than Appellant): <u>SEFF</u> B	OSTON.
Address (if not Appellant's): 1865 OLD HUDS	ON ROAD, ST. PAUL, MN 55119
Phone Numbers: Business Residence _	Cell
What Is Being Appealed and Wh	ny? Attachments Are Acceptable
Vacate Order/Condemnation/ Revocation of Fire C of O	
□ Summary/Vehicle Abatement	
Fire C of O Deficiency List #6 - WINDon) SIZE FOR ESCAPE WINDOWS IN SCEEPING ROOM
☐ Fire C of O: Only Egress Windows	
Code Enforcement Correction Notice	
□ Vacant Building Registration	
□ Other	



CITY OF SAINT PAUL Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806
 Telephone:
 651-266-8989

 Facsimile:
 651-266-8951

 Web:
 www.stpaul.gov/dsi

October 27, 2011

JEFF BOSTON MICHELLE BOSTON 1865 OLD HUDSON ROAD ST PAUL MN 55119-4336

FIRE INSPECTION CORRECTION NOTICE

RE:

144 LEXINGTON PKWY N

Residential Class: C

Dear Property Representative:

Your building was inspected on October 27, 2011 for the renewal of your Fire Certificate of Occupancy. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected prior to the re-inspection date. A re-inspection will be made on December 8, 2011 at 10:00 AM.

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional re-inspection fees.

YOU WILL BE RESPONSIBLE FOR NOTIFYING TENANTS IF ANY OF THE FOLLOWING LIST OF DEFICIENCIES ARE THEIR RESPONSIBILITY.

DEFICIENCY LIST

- 1. Basement steps SPLC 34.10 (3) 34.33(2) Provide an approved guardrail. Intermediate ballustrade must not be more than 4 inches apart. Intermediate rails must be provided if the height of the platform is more than 30 inches.
- 2. Exterior SPLC 34.09 (3), 34.32 (3) Repair and maintain the window in good condition.-Scrape and remove chipped and peeling paint. Repaint in a professional manner.
- 3. First floor south porch MSFC 605.5 Discontinue use of extension cords used in lieu of permanent wiring.
- 4. Garage SPLC 71.01 The address posted is not visible from street. (HN-1)
- 5. North side doors SPLC 34.09 (3) i Provide and maintain an approved one-inch throw single cylinder deadbolt lock.

North side doors - MSFC1026.1 - Provide and maintain an approved escape window from each sleeping room. The minimum size must be 5 square feet of glazed area with a minimum of 24

An Equal Opportunity Employer

inches of openable height and 20 inches of openable width. With a finished sill height not more than 48 inches. This work may require permit(s). Call DSI at (651)- 266-9090. Refer to the Escape Windows for Residential Occupancies handout for more information.-

East

19 h x 30 w Glazed 8.5 sq ft South
19 h x 30 w Glazed 8.5 sq ft Southwest
19 h x 30 w Glazed 8.5 sq ft

Northwest

19 h x 30 w Glazed 8.5 sq ft

- 7. North side doors MSFC 605.5.3 Immediately, discontinue use of frayed, deteriorated, damaged or spliced electrical cords.-Discontinue use of temporary decorative lighting.
- 8. Third floor MSFC 605.5 Discontinue use of extension cords used in lieu of permanent wiring.
- 9. SPLC 34.11 (6), 34.34 (3) Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.
- SPLC 39.02(c) Complete and sign the provided smoke detector affidavit and return it to this
 office.
- 11. UMC 504.6 Provide, repair or replace the dryer exhaust duct. Exhaust ducts for domestic clothes dryers shall be constructed of metal and shall have a smooth interior finish. The exhaust duct shall be a minimum nominal size of four inches (102 mm) in diameter. This work may require a permit(s). Call DSI at (651) 266-8989.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8688) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: rick.gavin@ci.stpaul.mn.us or call me at 651-266-8994. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Rick Gavin Fire Inspector