

APPLICATION FOR APPEAL

Saint Paul City Clerk

RECEIVED
APR 1 9 2012

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8560

Revised 3/7/2011

The City Clerk needs the following to process your appeal:

\$25 filing fee payable to the City of Sair (if cash: receipt number) Copy of the City-issued orders or letter are being appealed Attachments you may wish to include This appeal form completed Walk-In OR Mail-In	YOUR HEARING Date and Time:
Address Being Appealed:	
Number & Street: 649 We	City: St. PAul State: Ma Zip: 5510 3
Appellant/Applicant: GAYY Ne	Ison Email anelson homes by whoo, c
Appellant/Applicant: GAVY Ne Son Email gne son homes Gyrhoo, c Phone Numbers: Business 651-983-6789 Residence Cell 651-983-6789	
Signature: Jary Nelson Date: 4/17/12	
Name of Owner (if other than Appellant): Mary Brinker / Sheil A Brinker	
Address (if not Appellant's): 145 Hudson Rd #313	
Phone Numbers: Business	Residence 489-4903 Cell 308-1969
What Is Being Appealed and Why? Attachments Are Acceptable	
Vacate Order/Condemnation/	in a diameter disconsiste
Revocation of Fire C of O Summary/Vehicle Abatement	De want a timeextention
Fire C of O Deficiency List	some of the consist are
□ Fire C of O: Only Egress Windows	seing done through th
□ Code Enforcement Correction Notice	reing don't through th
□ Vacant Building Registration	
□ Other	
□ Other	



CITY OF SAINT PAUL Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806

 Telephone:
 651-266-8989

 Facsimile:
 651-266-8951

 Web:
 www.stpaul.gov/dsi

April 13, 2012

SHEILA M BRINKER Mary E Brinker 1145 HUDSON ROAD #313 ST PAUL MN 55106

Revocation of Fire Certificate of Occupancy and Order to Vacate

RE: 649 WESTERN AVE N

Dear Property Representative:

Your building was inspected on April 6, 2012, for the renewal of the Certificate of Occupancy. Since you have failed to comply with the applicable requirements, it has become necessary to revoke the Certificate of Occupancy in accordance with Section 40.06 of the Saint Paul Legislative Code.

A re-inspection will be made on May 1, 2012 or the property vacated.

The Saint Paul Legislative Code further provides that no building shall be occupied without a Certificate of Occupancy. Failure to immediately complete the following deficiency list or the building vacated may result in a criminal citation.

DEFICIENCY LIST

- 1. Exterior SPLC 34.09 (1) b,c, 34.32 (1) b,c Provide and maintain all exterior walls free from holes and deterioration. All wood exterior unprotected surfaces must be painted or protected from the elements and maintained in a professional manner free from chipped or peeling paint.
- 2. Exterior SPLC 34.09 (1) a, 34.32 (1) a Provide and maintain foundation elements to adequately support this building at all points.
- 3. Exterior-Front Steps SPLC 34.09 (2), 34.32(2) Repair or replace the damaged guardrail in an approved manner. This work requires a permit(s). Call DSI at (651) 266-9090.
- 4. Exterior-Front Steps SPLC 34.09 (2) 34.32 (2) Provide an approved handrail. The top of the handrail must be between 34 and 38 inches above the treads and run the entire length of the stair.
- 5. Exterior-Throughout SPLC 34.09 (3), 34.32 (3) Repair and maintain the window glass.
- 6. Exterior-Throughout SPLC 34.09 (3), 34.32 (3) Provide or repair and maintain the window screens.

- 7. Exterior-Throughout SPLC 34.08 (5), 34.31 (3) Repair, replace and maintain all exterior surfaces on fences, sheds, garages and other accessory structures free from holes and deterioration. Provide and maintain exterior unprotected surfaces painted or protected from the elements.
- 8. Exterior-Throughout SPLC 34.09 (2), 34.32(2) Repair or replace the unsafe stairways, porch, decks or railings in an approved manner. This work may require a permit(s). Call DSI at (651) 266-9090.
- 9. Interior- Unit 1 SPLC 34.23, MSFC 110.1 This occupancy is condemned as unfit for human habitation. This occupancy must not be used until re-inspected and approved by this office.-Condemned due to cracked furnace.
- 10. Interior-Basement SPLC 34.10 (3) 34.33(2) Provide an approved guardrail. Intermediate ballustrade must not be more than 4 inches apart. Intermediate rails must be provided if the height of the platform is more than 30 inches.
- 11. Interior-Basement SPLC 34.10 (3), 34.33(2) Provide an approved handrail. The top of the handrail must be between 34 and 38 inches above the treads and run the entire length of the stair.
- 12. Interior-Basement UMC 504.6 Provide, repair or replace the dryer exhaust duct. Exhaust ducts for domestic clothes dryers shall be constructed of metal and shall have a smooth interior finish. The exhaust duct shall be a minimum nominal size of four inches (102 mm) in diameter. This work may require a permit(s). Call DSI at (651) 266-8989.-Hire a licensed contractor to install the dryer vent to meet code. Remove screws and duct tape.
- 13. Interior-Closets throughout MSFC 605.1- All light fixtures shall be maintained with protective globes if originally equipped.-All closets must have globe covers on the light fixtures.
- 14. Interior-Front Entry- Unit 2 MSFC 605.1 Repair or replace damaged electrical fixtures. This work may require a permit(s). Call DSI at (651) 266-9090.-Repair or replace loose light fixture in the entry to unit 2.
- 15. Interior-Rear Entry/Exit Unit 2 SPLC 34.10 (7), 34.33 (6) Repair and maintain the floor in an approved manner.-Repair or replace the floor tile in the rear entry of unit 2.
- 16. Interior-Rear steps from Unit 2. SPLC 34.10 (3), 34.33(2) Repair or replace the unsafe stairway in an approved manner.-Repair or replace all broken steps to the exit in the back of unit 2.
- 17. Interior-Throughout SPLC 34.11 (6), 34.34 (3) Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.-Report received from Inspections Plus stating the gas controls defective, and the furnace is cracked. Immediately discontinue use until replaced under permit.
- 18. Interior-Throughout SPLC 34.19 Provide access to the inspector to all areas of the building.
- 19. Interior-Throughout SPLC 34.08 (10) Repair, replace and maintain exterior sidewalks, walkways and stairs.-Repair the damaged cement stairs at the rear of the building.
- 20. Interior-Throughout SPLC 34.10 (7), 34.33 (6) Repair and maintain the ceiling in an approved manner.-Patch and paint the holes and/or cracks in the ceilings throughout.

- 21. Interior-Throughout SPLC 34.10 (7), 34.33 (6) Repair and maintain the walls in an approved manner.-Patch and paint the holes and/or cracks in the walls throughout.
- 22. Interior-Throughout SPLC 34.09 (3) i Provide and maintain an approved one-inch throw single cylinder deadbolt lock.-Remove unapproved double keyed deadbolts and all slide bolt locks from exit doors.
- 23. Interior-Throughout SPLC 34.11 (6) Provide and maintain a minimum of 68 degrees F in all habitable rooms at all times.
- 24. Interior-Throughout MN Rules 1300.0180 Immediately discontinue use of unsafe heating appliance until repaired or replaced by a licensed contractor. This work may require a permit(s). Call DSI at (651) 266-9090. Red tags may not be removed except by fire department inspector. Repair or replace the cracked furnace under permit.
- 25. SPLC 39.02(c) Complete and sign the provided smoke detector affidavit and return it to this office.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8688) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: lisa.martin@ci.stpaul.mn.us or call me at 651-266-8988 between 6:30 - 8:30 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Lisa Martin Fire Inspector