


Date: October 30, 2012
File #: 09 - 312701
Folder Name: 606 MARYLAND AVE E
PIN: 292922120095



goes through intervening space, (kitchen)
door under 6' - therefore, can't be
counted as a 2nd exit

door under to
open through interior space (interior)

