

☐ Other (Fence Variance, Code Compliance, etc.)

APPLICATION FOR APPEAL

Saint Paul City Council – Legislative Hearings

RECEIVED

JUL 09 2015

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8585

We need the following to process your appeal: CITY CLE	ERK
\$25 filing fee (non-refundable) (payable to the City of Saint Paul) (if cash: receipt number) Copy of the City-issued orders/letter being appealed Attachments you may wish to include This appeal form completed Walk-In OR Mail-In for abatement orders only: Email OR Fax	HEARING DATE & TIME (provided by Legislative Hearing Office) Tuesday, July 14, 2015 Time 1:30 p.m. Location of Hearing: Room 330 City Hall/Courthouse
Address Being Appealed:	
	T Paul State: MN Zip: SS JE ail WINNIE CROSBIE @ EDINARGALTY, (Cell 612-741-9556 Date: 7/9/15
Name of Owner (if other than Appellant):	
Mailing Address if Not Appellant's: Doe HILL D	R, CHURCHVILLE, VA 24421
Phone Numbers: Business Residence 540 -3	37-8067 Cell
What Is Being Appealed and Why? Vacate Order/Condemnation/ Revocation of Fire C of O Summary/Vehicle Abatement	Attachments Are Acceptable
Fire C of O Deficiency List/Correction House is let	ed on Market Jon Sale
Code Enforcement Correction Notice	
Vacant Building Registration	



CITY OF SAINT PAUL Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806 Telephone: 651-266-8989 Facsimile: 651-266-8951 Web: <u>www.stpaul.gov/dsi</u>

June 29, 2015

WINNIE CROSBIE 4349 BROOKSIDE AVE S ST LOUIS PARK MN 55436-1547

FIRE INSPECTION CORRECTION NOTICE

RE:

2100 STILLWATER AVE

Ref. #113448

Residential Class: C

Dear Property Representative:

Your building was inspected on June 25, 2015 for the renewal of your Fire Certificate of Occupancy. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected prior to the re-inspection date.

A re-inspection will be made on August 3, 2015 at 11:15 AM.

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

YOU WILL BE RESPONSIBLE FOR NOTIFYING TENANTS IF ANY OF THE FOLLOWING LIST OF DEFICIENCIES ARE THEIR RESPONSIBILITY.

DEFICIENCY LIST

1. Exterior - Driveway - SPLC 34.08 (7) - All parking spaces shall be paved with asphalt, concrete, or durable dustless surfacing. Before any existing spaces may be paved, site plan approval must be obtained as specified in the St. Paul Zoning Code. Contact DSI Zoning at 651-266-8989.-Parking space/driveway is crumbling, cracked and missing in spots.

- 2. Exterior Front Entry SPLC 34.09 (3), 34.32 (3) Repair and maintain the door latch.- For front entry screen door
- 3. Exterior Front Entry MSFC 603.9- Call Xcel Energy at 1-800-895-4999 to provide vehicle impact protection for the gas meter.-For gas meter at front of prop.
- 4. Exterior Retaining Wall at Rear of Property SPLC 34.08(5), 34.32(3) All accessory structures including, but not limited to, detached garages, sheds, retaining walls and fences shall be maintained structurally sound and in good repair. Provide and maintain exterior unprotected surfaces painted or protected from the elements.-The retaining wall at the back of the property is showing signs of weakness, pushing out into neighboring lot, mortar missing in areas.
- 5. Interior Basement SPLC 34.10 (7), 34.34 (6) Repair and maintain the ceiling in an approved manner.-Replaced stained ceiling tiles or remove completely.
- 6. Interior Basement UMC 1346.703 Provide 30 inches clearance around all mechanical equipment.-Furnace and water heater.
- 7. Interior Basement SPLC 34.11, MSBC 2902.1, SPLC 34.17, MSPC 415.0220 Repair or replace and maintain all parts of the plumbing system to an operational condition.- Laundry sink faucet leaking.
- 8. Interior Basement Bathroom SPLC 34.10 (7), 34.34 (6) Repair and maintain the walls in an approved manner. Basement bathroom door opens into soffit inside bathroom-damaging the gypboard.
- 9. Interior Basement Laundry MSMC 504.6 Provide, repair or replace the dryer exhaust duct. Exhaust ducts for domestic clothes dryers shall be constructed of metal and shall have a smooth interior finish. The exhaust duct shall be a minimum nominal size of four inches (102 mm) in diameter and installed in accordance with the mechanical code. This work may require a permit(s). Call DSI at (651) 266-8989.-Dryer vent disconnected from dryer and not insulated per Energy Code.
- 10. Interior Combustible Storage MSFC 315.2.5 Fueled equipment, including but not limited to motorcycles, mopeds, lawn-care equipment and portable cooking equipment, shall not be stored, operator or repaired within a building.-Including charcoal and lighter fluid stored in closet, remove to outdoor storage location.
- 11. Interior Living Room Threshold SPLC 34.10 (7), 34.34 (6) Repair and maintain the floor in an approved manner.-Carpet tack strip exposed at threshold at living room.
- 12. SPLC 34.11 (6), 34.34 (3) Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.

13. SPLC 39.02(c) - Complete and sign the smoke detector affidavit and return it to this office.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8585) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: laura.huseby@ci.stpaul.mn.us or call me at 651-266-8998 between 7:30 a.m. - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Laura Huseby Fire Inspector

Reference Number 113448