

INSPECTION REQUEST

Address this form to: MAILING LIST - FORM4 (District Chief, and Yourself).

| | | |
|--|--|--|
| Date: | 01/20/2019 | |
| Property Address: | 1330 Blair Ave | |
| Owner Name: | Franciscan Brothers Of Peace | |
| Owner Phone: | 651-646-8586 | |
| Owner Address: | 1289 Lafond Ave St Paul MN 55104-2035 | |
| Occupant Name: | Community School of Excellence | |
| Occupant Phone: | | |
| Check the following corrections: | | |
| <input type="checkbox"/> Address Nos. <input type="checkbox"/> Exit Doors <input type="checkbox"/> Housekeeping <input checked="" type="checkbox"/> Keybox <input type="checkbox"/> Sprinkler System | <input type="checkbox"/> Hydrants <input type="checkbox"/> Hazardous Material <input type="checkbox"/> Fire Alarm System <input type="checkbox"/> Smoke Detector <input type="checkbox"/> Standpipe | <input type="checkbox"/> Fire Lane <input type="checkbox"/> Electrical <input type="checkbox"/> Fire Extinguishers <input type="checkbox"/> Heating Plant <input type="checkbox"/> Welding <input type="checkbox"/> OTHER _____ |
| Check the type of property: | <input type="checkbox"/> Single family or duplex <input type="checkbox"/> Multi family (3 Units or more) <input checked="" type="checkbox"/> Commercial | |
| Describe: | While responding to an alarm sounding due to discharged dry chemical extinguishers, it was discovered that there was no key to the fire panel room in the keybox. There was an internal lock box on the fire panel room door jamb, but there was no combination available for that lock box. | |
| Name: Brian Kroeger | Rank: District Chief | Company: C1B |
| Response: | | |
| Name: | Date: | Phone: |