

SPRWS Work Related Injuries
April -June 2022

SPRWS Claim #	Date of Injury	Division	Job Title	Injury Description	Body Part
22-013	4/04/22	Distribution	Vehicle Mechanic Supervisor	Employee slipped and twisted right knee.	Right Knee
22-014	4/07/22	Production	Water Utility Worker I	Employee was lifting large tree logs when he felt pain in his lower back.	Lower Back
22-015	5/05/22	Distribution	Water System Worker II	Employee was in a motor vehicle accident with another car that ran a stop sign and hit him on the passenger side of the vehicle. He experienced pain in his right knee following the accident.	Right Knee
22-016	5/09/22	Distribution	Water Utility Worker I	Employee was hammering two wood forms together when he missed the nail and hit his thumb.	Left Thumb
22-017	5/24/22	Distribution	Water Utility Worker I	Employee was reaching into the work truck toolbox when his left middle finger was cut by the open blade of a utility knife.	Left Middle Finger
22-018	6/03/22	Engineering	Intern	Employee was working in the field locating underground water utilities when the spray paint can nozzle broke off causing paint to spray onto the right side of his face and into his right eye.	Right Side of Face & Eye
22-019	6/17/22	Distribution	Water Utility Worker I	Employee was attempting to reach a rod on a 12-inch valve when the rod head became wedged between the valve and riser causing the employee to slip when he tried to turn it. He experienced pain in his left shoulder.	Left shoulder