## Work plan - Breakdoswn cost of rehabilation to be done in accordance with the Code Complaince inspection report

694 Sherburne Ave

Adress:

eek Of	Task	Contactor	Supplies/Materials On hand	Needed Supplies/Materials	Owner developer labor	Value of Cost
	Chimney	Owner		a bag Cement		200
1/10/2022						
1/15/2022	Grade Drain away	Owner	On hand dirt			200
1/20/2022	Basement stair	owner	On hand wood			100
1/23/2022	Hand Rail	Owner		2 X 8 Metals		300
1/27/2022	Strap support	Owner		2 pieces		100
2/1/2022		Owner		2 Windows		800.00
2/5/2022	Storm, Screen	Owner		1 roll Screen		300
2/10/2022	Hardware all lock	Owner				300
2/15/2022		Owner	on hand			300
2/20/2022	Damage door, storm screen	Owner				300
	Misc					2000
						4900