From: Bistodeau, Travis (CI-StPaul)
To: metriccsp@qmail.com

Cc: Moermond, Marcia (CI-StPaul); Vanq, Mai (CI-StPaul); Ubl, Stephen (CI-StPaul); carolyn brown

Subject: 936 Jefferson

Date: Friday, June 25, 2021 10:19:38 AM

Attachments: image003.png

image004.png image005.png

936 Jefferson Inspection Request.docx

image002.png

Greetings Mr. Giles,

Thank you for taking the time to discuss the above address with me yesterday.

Our records reveal the following facts:

- Building Permit 18-114571 was issued to Innovative Building Authority on 10/17/18
- Per the MN Building Code, it is the permit holder's responsibility to call for inspections to ensure work has been completed to the satisfaction of this code. To date, the permit holder has not requested any inspection for this permit.
- 4/15/21-Inspector Sutter sent a letter to the permit holder requesting an inspection (attached)
- 4/20/21-Inspector Stensland met with the owner on-site and informed the owner that the contractor would be notified of the need for an inspection

Hopefully, this record will be helpful should you or your daughter choose to take legal action against this contractor.

In addition, since raising this issue to the City of Saint Paul Building Official yesterday, the Building Inspector will also be sending a correction order to the contractor to address deficiencies identified under this permit. This may also result in a response from the contractor soon.

I hope this is helpful.

Thank you,



Travis Bistodeau

Pronouns: he/him/his Deputy Director Department of Safety and Inspections 375 Jackson Street, Suite 220 Saint Paul, MN 55102

P: 651-266-1922 C: 651-262-7698

Email: travis.bistodeau@ci.stpaul.mn.us



DSI's Mission: To preserve and improve the quality of life in Saint Paul by protecting and

promoting public health and safety for all.