Work plan - Breakdoswn cost of rehabilation to be done in accordance with the Code Complaince inspection report

.

Adress: 694 Sherburne Ave

.

.

Week Of	Task	Contactor	Supplies/Materials On hand S	Needed Supplies/Materials	Owner developer labor	Value of Cost
1/10/2022	Chimney	Owner		a bag Cement		200
1/15/2022	Grade Drain away	Owner	On hand dirt			400
1/20/2022	Basement stair	owner	On hand wood			100
1/23/2022	Hand Rail	Owner		2 X 8 Metals		300
1/27/2022	Strap support stringer	Owner		2 pieces		100
2/1/2022		Owner		2 Windows		1000.00
2/5/2022	Storm, Screen	Owner		1 roll Screen		800
2/10/2022	Hardware all lock	Gwilei				300
2/15/2022	Exit door open from inside	Owner	on hand			300
2/20/2022	Damage door, storm screen	Owner				600
	Misc					2000
						6100