

Date: May 11, 2010
File #: 10 - 319910
Folder Name: 838 ROBERT ST S
PIN: 082822340104

HP District:
Property Name:
Survey Info:



West side, posting



Front posting



Unapproved electrical wiring on front porch

Appears to be extension cord used for wiring



Unapproved electrical wiring on front porch



Rear posting



Unapproved electrical wiring on rear porch

Date: May 11, 2010
File #: 10 - 319910
Folder Name: 838 ROBERT ST S
PIN: 082822340104

HP District:
Property Name:
Survey Info:



Unapproved electrical wiring on rear porch



Unapproved electrical wiring on rear porch



East and south sides, posting



Garage



West and south sides



North and west sides

Date: January 04, 2012
File #: 10 - 319910
Folder Name: 838 ROBERT ST S
PIN: 082822340104

HP District:
Property Name:
Survey Info:



Missing fixture, open electric, exposed wiring



Mold, auto parts storage



Mold, auto parts storage



Mold



Mold



Burst expansion tank for the hot water heating system

Date: January 04, 2012
File #: 10 - 319910
Folder Name: 838 ROBERT ST S
PIN: 082822340104

HP District:
Property Name:
Survey Info:



Heating plant



Water damaged wall, mold



Mold in basement



Missing hand rail for basement steps



Missing cover plate, exposed wiring, damaged door frame



Missing floor board, missing wall mounted heater, open Wall, cut gas line for heater

Date: January 04, 2012
File #: 10 - 319910
Folder Name: 838 ROBERT ST S
PIN: 082822340104

HP District:
Property Name:
Survey Info:




Blown out hot water heating line



Blown out hot water heating line



Open foundation wall, shifted block



Missing cover plate, exposed wiring



Missing cover plate; exposed wiring



Chipped/peeling paint, dry water trap, open floor covering

Date: January 04, 2012
File #: 10 - 319910
Folder Name: 838 ROBERT ST S
PIN: 082822340104

HP District:
Property Name:
Survey Info:



No gfc protected outlets



Improper electrical splice, open plumbing



Water damaged wall, open water line, mold



North and west sides



Gas meter removed



West and south side

Date: January 04, 2012
File #: 10 - 319910
Folder Name: 838 ROBERT ST S
PIN: 082822340104

HP District:
Property Name:
Survey Info:



Garage



South and east sides



Electric service yellow tagged off



Close view of open foundation, shifted foundation block and missing mortar joint, debris pile