

Date: October 20, 2011
File #: 11 - 290184
Folder Name: 317 BAKER ST W
PIN: 072822310010

HP District:
Property Name:
Survey Info:



North and east sides



Front (south side) posting



Shed



East side posting



South and east sides



South side

Date: October 20, 2011
File #: 11 - 290184
Folder Name: 317 BAKER ST W
PIN: 072822310010

HP District:
Property Name:
Survey Info:



South and west sides, posting

Date: January 11, 2012
File #: 11 - 290184
Folder Name: 317 BAKER ST W
PIN: 072822310010

HP District:
Property Name:
Survey Info:

The following photographs were taken on or about September 27, 20011, for a condemnation action.



Date: January 11, 2012
File #: 11 - 290184
Folder Name: 317 BAKER ST W
PIN: 072822310010

HP District:
Property Name:
Survey Info:




Date: January 11, 2012
File #: 11 - 290184
Folder Name: 317 BAKER ST W
PIN: 072822310010

HP District:
Property Name:
Survey Info:



Date: January 11, 2012
File #: 11 - 290184
Folder Name: 317 BAKER ST W
PIN: 072822310010

HP District:
Property Name:
Survey Info:



Date: January 11, 2012
File #: 11 - 290184
Folder Name: 317 BAKER ST W
PIN: 072822310010

HP District:
Property Name:
Survey Info:



Date: January 11, 2012
File #: 11 - 290184
Folder Name: 317 BAKER ST W
PIN: 072822310010

HP District:
Property Name:
Survey Info:



Date: January 11, 2012
File #: 11 - 290184
Folder Name: 317 BAKER ST W
PIN: 072822310010

HP District:
Property Name:
Survey Info:

The following pictures were taken on January 11, 2012



Rot damaged, open eave



Deteriorated steps



Rot damaged window, rain leader drains onto window



South and east sides



Deteriorated roof covering



Rain leader drains over wall and at foundation

Date: January 11, 2012
File #: 11 - 290184
Folder Name: 317 BAKER ST W
PIN: 072822310010

HP District:
Property Name:
Survey Info:



Rot damaged, open eave and wall



Rot damaged window, water staining on interior side of window



Rot damaged eave, missing siding



Improperly abandoned window, open wall, chipped/peeling paint



Date: January 11, 2012
File #: 11 - 290184
Folder Name: 317 BAKER ST W
PIN: 072822310010

HP District:
Property Name:
Survey Info:

Rot and rodent damaged, open eave, deteriorated roof covering