

Form 4 1006 3rd St E report

The following inspection request was submitted on 09 Feb 2021 16:08:

Owner Name: CERVELIO QUEZADA

Address: 1006 3RD ST E

Property Type: single-family

No Heat: on

Utility Shut Off: on

Housekeeping/Excessive Content: on

Other: Condemned residence with reports of people living in basement Situation Description: House was last visited approx one week ago with no issues noted. Broken window on side A, fire occurred in the basement, frozen pipes with significant amount of water damage to dwelling, gas and electricity shut off by Xcel, house is on condemned list per SPPD officers on scene.

Name: S.Sampson

Rank: Dep

Company: CAR 7