

The City Clerk needs the following to process your Cappea CLERK

APPLICATION FOR APPEAL

Saint Paul City Clerk

RECEIVED FEB 2 2 2012 310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8560

\$25 filing fee payable to the City of Saint Paul (if cash: receipt number) Copy of the City-issued orders or letter which are being appealed Attachments you may wish to include This appeal form completed Walk-In OR Mail-In	YOUR HEARING Date and Time: Tuesday, 3-6-12 Time / 30 Location of Hearing: Room 330 City Hall/Courthouse
Address Being Appealed:	
Number & Street: 447 Wh.tall St City: St Paul State: Ma Zip: 55101	
Appellant/Applicant: Jereny Hollingswork Email jereny@twisCity resicon	
Phone Numbers: Business 952 210 4681 Resid	dence Cell 953 2104981
Signature:	Date: <u>Z</u> Zo îZ
Name of Owner (if other than Appellant): Any Jerse	
Address (if not Appellant's): Po. Box 693 Lyons Co 80540	
Phone Numbers: Business Resid	dence Cell
What Is Being Appealed and Why? Attachments Are Acceptable	
Vacate Order/Condemnation/ Revocation of Fire C of O	ciercy List:
□ Summary/Vehicle Abatement	+8 Window Size
□ Fire C of O Deficiency List	12 Window Size
☐ Fire C of O: Only Egress Windows	
	solour are onegonal
□ Vacant Building Registration	V
□ Other	



CITY OF SAINT PAUL Christopher B. Coleman, Mayor 375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806
 Telephone:
 651-266-8989

 Facsimile:
 651-266-8951

 Web:
 www.stpaul.gov/dsi

February 3, 2012

AMY JENSEN Po Box 693 Lyons CO 80540-0693

FIRE INSPECTION CORRECTION NOTICE

RE:

447 WHITALL ST

Ref. #113996

Residential Class: C

Dear Property Representative:

Your building was inspected on February 3, 2012 for the renewal of your Fire Certificate of Occupancy. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected prior to the re-inspection date. A reinspection will be made on March 5, 2012 at 10;00 A.M..

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

YOU WILL BE RESPONSIBLE FOR NOTIFYING TENANTS IF ANY OF THE FOLLOWING LIST OF DEFICIENCIES ARE THEIR RESPONSIBILITY.

DEFICIENCY LIST

- 1. Basement SPLC 34.23, MSFC 110.1 The Basement is condemned as unsafe or dangerous when being used for sleeping purposes. The Basement cannot be used for sleeping purposes until re-inspected and approved by this office.-Remove bedding and mattresses from basement. No egress
- 2. Basement SPLC 34.10 (3), 34.33(2) Provide an approved handrail. The top of the handrail must be between 34 and 38 inches above the treads and run the entire length of the stair.

An Equal Opportunity Employer

- 3. Building SPLC 34.09 (3), 34.32 (3) Provide or repair and maintain the window screens.
- 4. Garage SPLC 34.08 (5), 34.31 (3) Repair, replace and maintain all exterior surfaces on fences, sheds, garages and other accessory structures free from holes and deterioration. Provide and maintain exterior unprotected surfaces painted or protected from the elements.
- 5. Interior stairway MSFC 1011.2 Remove the materials that cause an exit obstruction. Maintain a clear and unobstructed exitway.-remove all storage from all landings and stairways
- 6. Rear Stairway SPLC 34.10 (3), 34.33(2) Provide an approved handrail. The top of the handrail must be between 34 and 38 inches above the treads and run the entire length of the stair.
- 7. Stairway leading to the upstairs Unit. SPLC 34.10 (3), 34.33(2) Repair or replace the unsafe stairway in an approved manner. Remove or secure all hazards such as carpet nails that protrude up on stairway.
- 8. Unit Downstairs MSFC1026.1 Provide and maintain an approved escape window from each sleeping room. The minimum size must be 5 square feet of glazed area with a minimum of 24 inches of openable height and 20 inches of openable width. With a finished sill height not more than 48 inches. This work may require permit(s). Call DSI at (651)- 266-9090. Refer to the Escape Windows for Residential Occupancies handout for more information.-casement windows12inches openable width. Openable height is 48inches. Sill is 17 inches. Glazed is 14inches in width by 44inches in height.
- 9. Unit Upstairs MSFC 605.6 Provide electrical cover plates to all outlets, switches and junction boxes where missing.
- 10. Unit Upstairs MSFC 605.4 Discontinue use of all multi-plug adapters.-Kitchen
- 11. Unit Upstairs MSFC 605.1- All light fixtures shall be maintained with protective globes if originally equipped.
- 12. Unit Upstairs MSFC1026.1 Provide and maintain an approved escape window from each sleeping room. The minimum size must be 5 square feet of glazed area with a minimum of 24 inches of openable height and 20 inches of openable width. With a finished sill height not more than 48 inches. This work may require permit(s). Call DSI at (651)- 266-9090. Refer to the Escape Windows for Residential Occupancies handout for more information.-casement windows 19inches in openable width. Sill 29inches. Openable height 44inches. Glazed 18inches in width by 46inhces height.
- 13. Unit downstairs MSFC 605.1 Remove unapproved exposed wiring and install in accordance with the electrical code. This work may require a permit(s). Call DSI at (651) 266-9090.-Living room

- 14. Unit downstairs MSFC 605.5 Discontinue use of extension cords used in lieu of permanent wiring.-Various locations
- Unit downstairs MN Stat 299F.18 Immediately remove and discontinue excessive accumulation of combustible materials.-Reduce by 50%
- 16. Unit downstairs MN Stat. 299F.362 Immediately provide and maintain a smoke detector located outside each sleeping area.
- 17. Unit downstairs SPLC 34.09 (3) i Provide and maintain an approved one-inch throw single cylinder deadbolt lock.-Rear Exit door
- 18. Unit downstairs MN State Statute 299F.50 Immediately provide and maintain an approved Carbon Monoxide Alarm in a location within ten (10) feet of each sleeping area. Installation shall be in accordance with manufacturers instructions.
- 19. SPLC 34.11 (6), 34.34 (3) Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.
- 20. SPLC 39.02(c) Complete and sign the provided smoke detector affidavit and return it to this office.
- MSFC 307.1 Fire Prevention has been receiving complaints regarding fires conducted on your property. All fires on the ground must be a minimum of 25 feet from structures or contained in a grill or outdoor fireplace. Wind speeds must be under 10 mph, constantly attended, a means of extinguishment must be provided. Only natural firewood can be burned (no construction materials, brush or waste materials), and fire shall be extinguished if the smoke is deemed a nuisance. A citation will be issued for non-compliance.
- 22. UMC 504.6 Provide, repair or replace the dryer exhaust duct. Exhaust ducts for domestic clothes dryers shall be constructed of metal and shall have a smooth interior finish. The exhaust duct shall be a minimum nominal size of four inches (102 mm) in diameter. This work will require a permit(s). Call DSI at (651) 266-8989.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8688) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: james.thomas@ci.stpaul.mn.us or call me at 651-266-8983 between 7:30 a.m. - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

4

Sincerely,

James Thomas Fire Inspector

Reference Number 113996