

□ Other

APPLICATION FOR APPEAL

RECEIVED

MAR 1 2 2012

CITY CLERK

Saint Paul City Clerk

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8560

The City Clerk needs the following to pro	ocess your appeal:
\$25 filing fee payable to the City of S (if cash: receipt number) Copy of the City-issued orders or lett are being appealed Attachments you may wish to includ This appeal form completed Walk-In OR Mail-In	YOUR HEARING Date and Time: ter which Tuesday, 3-27-12
Address Being Appeal	ed:
	Ave City: St Paul State: MN zip: 55106 land Email Tim Qedeck. net
Phone Numbers: Business 651-344-	1849 Residence Cell
Signature:	Date: 3/12/2012
Name of Owner (if other than Appellant):	
Address (if not Appellant's):	
Phone Numbers: Business	Residence Cell
What Is Being Appealed and Why? Attachments Are Acceptable	
□ Vacate Order/Condemnation/ Revocation of Fire C of O	
□ Summary/Vehicle Abatement	
Fire C of O Deficiency List	items 12,#1 #449 integral to repairs of previous
□ Fire C of O: Only Egress Windows	approved extension
□ Code Enforcement Correction Notice	f ·
□ Vacant Building Registration	

Appealing:

Items #1, 2, 4, and #9 are integral to planned repairs previously extended until July 1, 2012. It makes no sense to do these items before fixing the cause. Also, tenant is 87 years old and these repairs have to be planned around his medical needs and lifestyle. We have planned repairs in accordance to those needs, and need to have these items considered as a single extension.

Tim Copeland



CITY OF SAINT PAUL Christopher B. Coleman, Mayor 375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806

 Telephone:
 651-266-8989

 Facsimile:
 651-266-8951

 Web:
 www.stpaul.gov/dsi

March 5, 2012

TIMOTHY S COPELAND 2307 BUFFALO ST WHITE BEAR TNSP MN 55110-2324

RE: RE-INSPECTION FIRE CERTIFICATE OF OCCUPANCY WITH DEFICIENCIES 1501 YORK AVE

Ref. # 113097

Dear Property Representative: Attached is a copy of the appeals letters that does not detail the ceiling extension nor the windows.

Your building was re-inspected for the Fire Certificate of Occupancy on March 5, 2012. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected immediately. A reinspection will be made on March 22, 2012 at 11:45A.M..

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

DEFICIENCY LIST

- 1. Bedroom North Side MSFC1026.1 Provide and maintain an approved escape window from each sleeping room. The minimum size must be 5 square feet of glazed area with a minimum of 24 inches of openable height and 20 inches of openable width. With a finished sill height not more than 48 inches. This work may require permit(s). Call DSI at (651)- 266-9090. Refer to the Escape Windows for Residential Occupanices handout for more information.-The openable height of the window is 22 inches and the openable with of the window is 27 inches. Unable to measure the sill . Glazed is 44 inghes in height by 25 inches in width approx. There are beds jamed up against the windows that need to be moved so measurements can be done for the windows.
- 2. Bedroom south West Side SPLC 34.10 (7), 34.33 (6) Repair and maintain the ceiling in an approved manner.-Repair or replace the damaged or deteriorated ceiling. Paint the ceiling. Patch the holes and/or cracks in the ceiling.
- 3. Duct is plastic UMC 504.6 Provide, repair or replace the dryer exhaust duct. Exhaust ducts for domestic clothes dryers shall be constructed of metal and shall have a smooth An Equal Opportunity Employer

interior finish. The exhaust duct shall be a minimum nominal size of four inches (102 mm) in diameter. This work WILL require a permit(s). Call DSI at (651) 266-8989.-The owner replace the dryer duct without a permit. There are screws into the duct and the duct itself is not installed to code and installed without a permit.

- 4. South West Bedroom MSFC1026.1 Provide and maintain an approved escape window from each sleeping room. The minimum size must be 5 square feet of glazed area with a minimum of 24 inches of openable height and 20 inches of openable width. With a finished sill height not more than 48 inches. This work may require permit(s). Call DSI at (651)- 266-9090. Refer to the Escape Windows for Residential Occupanices handout for more information.-Windows do open but the bedroom window on the south side has to have window sash cords unable to measure.
- 5. Various locations MSFC 605.4 Discontinue use of all multi-plug adapters.
- 6. Various locations MSFC 605.5 Discontinue use of extension cords used in lieu of permanent wiring.
- 7. SPLC 34.11 (6), 34.34 (3) Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.
- 8. SPLC 34.09 (1) e, 34.32 (1) d Provide and maintained the roof weather tight and free from defects.-July 1, 2012 per LHO
- 9. SPLC 34.09 (3), 34.32 (3) Repair and maintain the window sash cords.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8688) and must be filed within 10 days of the date of the original orders.

If you have any questions, email me at james.thomas@ci.stpaul.mn.us or call me at 651-266-8983 between 7:30 a.m - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

James Thomas Fire Inspector Ref. # 113097