

APPLICATION FOR APPEAL

Saint Paul City Clerk

RECEIVED

MAR 28 2012

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8560

CITY CLERK The City Clerk needs the following to process your appeal:

\$25 filing fee payable to the City of Saint Paul (if cash: receipt number_____)

Copy of the City-issued orders or letter which are being appealed

Attachments you may wish to include

This appeal form completed

🗆 Walk-In OR 🖫 Mail-In

YOUR HEARING Date and Time:	
Tuesday, 4-10-12	
Time	
Location of Hearing:	
Room 330 City Hall/Courthouse	

Address Being Appealed:

Number & Street: 1233 Bradley St	City: <u>57 Aul</u> State: <u>MN</u> Zip: <u>55 (30</u>
Appellant/Applicant: Gajpov Jang	Email <u>Charayang@comcast.net</u>
Phone Numbers: Business	Residence 763-315-1854 Cell 651-442-7863
Signature: Lipor n.	Date: 3 26 (12
Name of Owner (if other than Appellant):	
Address (if not Appellant's):	
Phone Numbers: Business	Residence Cell

What Is Being Appealed and Why? Attachments Are Acceptable

- □ Vacate Order/Condemnation/
 Revocation of Fire C of O
- □ Summary/Vehicle Abatement
- **★** Fire C of O Deficiency List
- ☐ Fire C of O: Only Egress Windows
- □ Code Enforcement Correction Notice
- □ Vacant Building Registration
- □ Other

I would like to appeal and request a variance for
#2 on the deficiency list enclosed. The window is the
original window that came with the house and
has previously been acceptable for past Cofo.
With the exception of the size, the window is still
in operable condition.

DEPARTMENT OF SAFETY AND IN SPECT ONS Fire Inspection Division Ricardo X. Cervantes, Director



CITY OF SAINT PAUL Christopher B. Coleman, Mayor 375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806 Telephone: 651-266-8989 Facsimile: 651-266-8951 Web: www.stpaul.gov/dsi

March 14, 2012

GAJPOV N YANG 9311 BALSAM FIR AVE N BROOKLYN PARK MN 55443

FIRE INSPECTION CORRECTION NOTICE

RE:

1233 BRADLEY ST

Ref. #101378

Residential Class: C

Dear Property Representative:

Your building was inspected on March 14, 2012 for the renewal of your Fire Certificate of Occupancy. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected prior to the re-inspection date.

A re-inspection will be made on April 13, 2012 at 11:00 am.

Failure to comply may result in a criminal citation or the revocation of the fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

YOU WILL BE RESPONSIBLE FOR NOTIFYING TENANTS IF ANY OF THE FOLLOWING LIST OF DEFICIENCIES ARE THEIR RESPONSIBILIT.

DEFICIENCY LIST

- 1. 1st Floor Rear room MSFC 605.4 Discontinue use of all multi-plug adapters.-Power strip plugged into power strip. Remove.
- 2. 2nd Floor Northwest bedroom MSFC1026.1 Provide and maintain an approved escape window from each sleeping room. The minimum size must be 5 square feet of glazed area with a minimum of 24 inches of openable height and 20 inches of openable width. With a finished sill height not more than 48 inches. This work may require permit (s). Call DSI at (651)-266-9090. Refer to the Escape Windows for Residential Occupanic s handout for more information.-Double hung window opening.

An Equal Opportunity Employer

H 22 in. - W 27 in. Glazed area. H 54 in. - W 24 in.

- 3. Basement SPLC 34.11(5), 34.34(2), SPC 4715.0200Q Provide acciquate hot water between 120 degrees F and 130 degrees F.-Hot water 141 F.
- 4. Basement SPLC 34.12 (2), 34.35 (1) Repair and maintain all required and supplied equipment in an operative and safe condition.-Smoke detector is chirping. Explace battery.
- 5. Basement stairs MSFC 1011.2 Remove the materials that cause a rexit obstruction. Maintain a clear and unobstructed exitway.
- 6. Front steps SPLC 34.09 (2), 34.32(2) Repair or replace the unsafe stairways, porch, decks or railings in an approved manner. This work may require a permit(s. Call DSI at (651) 266-9090.-Replace decaying wood.
- Rear porch NEC 440.13 For cord-connected equipment such as nom air conditioners, household refrigerators and freezers, drinking water coolers, and beverage dispensers, a separable connector or an attachment plug and receptable shall be permitted to serve as the disconnecting means. The appliance must plug directly into a permanent of tlet.-Freezer on extension cord. Must be plugged directly into wall outlet.
- 8. Rear porch doors MSFC 1011.2 Remove the materials that cause an exit obstruction. Maintain a clear and unobstructed exitway.
- 9. Stairway to 2nd floor. MSFC 1011.2 Remove the materials that cause an exit obstruction. Maintain a clear and unobstructed exitway.
- Thru out SPLC 34.09 (3), 34.32 (3) Provide or repair and maintain the window screen.
- SPLC 34.11 (6), 34.34 (3) Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.
- 12. SPLC 39.02(c) Complete and sign the provided smoke detector affidavit and return it to this office.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the vicilations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8688) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: mike.cassidy@ci.stpaul.mn.us or all me at