

WORK PLAN - BREAKDOWN COST OF REHABILITATION

(To be done in accordance with the Code Compliance Inspection Report) Address: 666 Arlington Avenue East, Saint Paul

WEEK OF	TASKS	CONTRACTOR	Supplies/Materials on hand (if any)	Needed Supplies/Materials	Owner/Developer Labor	Value of Cost	Completed	In Progress
8/2/2021	item 1	none	none needed	none	Nichole Ruiz	\$0	✓	
8/2/2021	item 2	none	none needed	none	Aaron Stephenson	\$0	✓	
8/2/2021	item 3	none	none needed	none	Nichole Ruiz	\$0	✓	
8/2/2021	item 4	none	paint, a bagster, some cleaning supplies on hand	bagsters to remove debris, cleaning supplies	Nichole Ruiz	roughly \$210 per bagster, cleaning supplies and paint as needed / unsure		✓
8/2/2021	item 5	none	none needed	none	Nichole Ruiz	\$0	✓	
8/9/2021	item 6	Damian Pelletier	some tiles, paint, linoleum, wood paneling	not sure yet	Damian Pelletier	unknown		
8/2/2021	item 7	none	rakes, shovels, etc	none	Nichole Ruiz	\$0		✓
8/16/2021	item 8	Mat Graske	paint, brushes, etc	tbd	Mat Graske	unknown		
8/2/2021	item 9	Eric Ransom	screen and handle	none	Eric Ransom	\$18	✓	
8/23/2021	item 10	Mike Rodger	paint, brushes, etc	unknown	Mike Rodger	tbd		
8/9/2021	item 11	Damian Pelletier	paint, brushes, etc	none	Damian Pelletier	\$35		
8/16/2021	item 12	Mat Graske	hammer, nails, etc	none	Mat Graske	\$0		
8/2/2021	item 13	none	none needed	none	Nichole Ruiz	\$0	✓	
8/30/2021	item 14	none	storage bins, shelving	none	Nichole Ruiz	\$0		✓
8/2/2021	item 15	none	none	none	Mike Rodger	\$0	✓	
8/2/2021	item 16	none	garbage bins	none	Nichole Ruiz	\$0	✓	
8/2/2021	item 17	none	smoke detectors	none	Nichole Ruiz	\$135	✓	
8/2/2021	item 18	none	CO2 detectors	none	Nichole Ruiz	\$80	✓	
8/4/2021	item 19	Ben King	deed	official copy?	Nichole Ruiz / Pamela Brown	\$53		✓
tbd	item 20	dsi	unsure	unsure	tbd	tbd		
8/2/2021	item 21	none	traps, fly strips, etc	none	Nichole Ruiz	\$200	✓	
8/18/2021	item 22	Arcade Animal Hospital	none	dog licenses	Nichole Ruiz	\$240		✓

WORK PLAN - BREAKDOWN COST OF REHABILITATION

(To be done in accordance with the Code Compliance Inspection Report) Address: 666 Arlington Avenue East, Saint Paul

8/2/2021	item 23	none	traps, fly strips, etc	none	Nichole Ruiz / Mike Rodger	\$0	✓	

Total Project Cost: \$ _____

Note: (Code Enforcement Officers estimate the cost to repair this structure is \$ _____ to \$ _____).