

From: [Zimny, Joanna \(CI-StPaul\)](#)
To: figgiano@comcast.net
Cc: [HECTOR FLORES](#); [John Flores](#)
Subject: 575 Park
Date: Wednesday, October 5, 2022 9:14:00 AM
Attachments: [image001.png](#)
Importance: High

Mr. Viggiano, et al,

The Hearing officer has been doing some follow-up on your property at 575 Park and after speaking with the Senior Plumbing inspector and Building Official it appears the property has the following deficiencies that still need to be addressed:

- **chimney liner required**
- **vent clothes dryer to code**
- **provide adequate combustion air**

Once these are addressed a Mechanical Pipefitter or Plumbing inspector will need to be consulted before the gas meter can be unlocked.

If your contractors have specific questions about this they can reach out to:

Steve Fernlund

Senior Plumbing Inspector

Department of Safety and Inspections

375 Jackson Street, Suite 220

Saint Paul, MN 55102

P: 651-266-9052

steve.fernlund@ci.stpaul.mn.us

Let me know if you have questions, and please confirm receipt.

Thanks,
Joanna



Joanna Zimny

Legislative Hearing Executive Assistant

Legislative Hearing Office

Pronouns: she/her/hers

Saint Paul City Hall

Suite 310

15 W. Kellogg Blvd.

Saint Paul, MN 55102

P: 651-266-8585

joanna.zimny@ci.stpaul.mn.us

www.StPaul.gov



Please consider the environment before printing this email