| A TUNING | APPLICA | FION FOR APPEAL |
|---|--|---|
| COLUMNIA O | REC | y Council – Legislative Hearings 310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8585 |
| We need the following to process your appeal: CITY CLERK | | |
| | \$25 filing fee (non-refundable) (payable to the City of Saint I (if cash: receipt number) Copy of the City-issued orders/letter being appealed Attachments you may wish to include This appeal form completed Walk-In OR <u>Mail-In-Dropped off</u> for abatement orders only: <u>O Email</u> OR <u>O Fax</u> | Paul) HEARING DATE & TIME (provided by Legislative Hearing Office) Tuesday, <u>June 8, 2021</u> Time <u>1:30 p.m. 4 3:00 p.m.</u> Location of Hearing: Room 330 City Hall/Courthouse Teleconference |
| Address Being Appealed: Number & Street: 240 Chester Street City: St. Paul State: MN Zip: 55107 | | |
| Appellant/Applicant: Americold Logistics, LLC Email Terry.Hopkins@americold.com | | |
| Appellant/Applicant: Email Email Email 6512337322 | | |
| | ne Numbers: Business Residence Residence | _{Cell} 6512337322 _{Date:} May 21, 2021 |
| Name of Owner (if other than Appellant): | | |
| Mailing Address if Not Appellant's: | | |
| | one Numbers: Business Residence | |
| What Is Being Appealed and Why? Attachments Are Acceptable | | |
| Vacate Order/Condemnation/ Revocation of Fire C of OComments:Please see the accompanying attachment. | | |
| O Summary/Vehicle Abatement | | |
| • Fire C of O Deficiency List/Correction | | |
| O Code Enforcement Correction Notice | | |
| O Vacant Building Registration | | |
| O Other (Fence Variance, Code Compliance, etc.) | | |

Attachment to Application for Appeal of:

Americold Logistics, LLC (identified on the Fire Correction Inspection Notice as "Atlas Cold Storage").

This Application serves as Americold Logistics, LLC's appeal of Deficiency List Item Number 4, which contends that Americold is in violation of MSFC 3205.5. Americold believes the deficiency is unwarranted for several reasons:

- (1) Americold benefits from the grandfathering provisions of the Minnesota State Fire Code (MSFC 102), and it (along with its predecessors) has safely operated the facility in its current construction for over 4 decades without danger to life or property;
- (2) Americold is identified as an S-2 occupancy by the Minnesota State Fire Code and the Minnesota State Building Code, which does not typically necessitate installation of an automatic sprinkler system (MSFC 903.2, MSBC 903.1); and
- (3) Strict compliance with the Fire Official's interpretation of Minnesota State Fire Code is impracticable because it would require *either* that Americold engineer an automatic sprinkler system that could be installed throughout its facility, *or* that Americold give up almost half of its storage capability. Neither of these options is economically viable—and therefore the facility qualifies for the modification provisions of MSFC 104.8.

Americold Logistics, LLC operates a cold storage warehouse at 240 Chester Street in St. Paul, Minnesota. There, Americold utilizes a palletized racking system to store frozen food products at heights of twenty to twenty-four feet. Americold and its predecessors have operated this cold storage facility in the same manner since at least the mid-1970s, shortly after the facility was constructed. Today, as was the case during the original construction, the facility sits at least one hundred and twenty feet away from neighboring properties as demonstrated by the attached facility site map.

Though not always owned or operated by Americold, the facility has never undergone significant renovation, nor has it been used for any purpose other than the cold storage of food products. Since Americold has owned and/or operated the facility, it has always maintained a current and valid Fire Certificate of Occupancy. Americold is not aware of any amendments to either the Minnesota State Fire Code or the Minnesota State Building Code that would now render its certificate of occupancy deficient.

Lastly, the commercial viability of the property as a cold storage facility is largely dependent on being able to utilize the full storage capacity of the building. Deficiency List Item Number 4's insistence that storage be reduced to 12 feet eliminates nearly 50% of the storage capacity, which hamstrings Americold's ability to meet its customers' storage needs—despite having safely done so for nearly four decades.

For at least these reasons, Americold appeals Deficiency List Item Number 4.

DEPARTMENT OF SAFETY AND INSPECTIONS Fire Inspection Division *Ricardo X. Cervantes, Director*



CITY OF SAINT PAUL

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806
 Telephone:
 651-266-8989

 Facsimile:
 651-266-8951

 Web:
 www.stpaul.gov/dsi

May 13, 2021

JOHN BRISSON ATLAS COLD STORAGE 240 CHESTER STREET ST PAUL MN 55107

FIRE INSPECTION CORRECTION NOTICE

RE: 236 CHESTER ST Ref. #35410

Dear Property Representative:

Your building was inspected on May 11, 2021 for the renewal of your Fire Certificate of Occupancy. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected prior to the re-inspection date. A re-inspection will be made on or after June 14, 2021.

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

YOU WILL BE RESPONSIBLE FOR NOTIFYING TENANTS IF ANY OF THE FOLLOWING LIST OF DEFICIENCIES ARE THEIR RESPONSIBILITY.

DEFICIENCY LIST

e.,

- EXTERIOR THROUGHOUT MSFC 5003.5 Provide NFPA 704 hazard identification placards.
 -Multiple faded placards throughout the property. Replace the faded placards.
- FIRE ALARM SYSTEM DOCUMENTATION MSFC 907.8 Provide required annual maintenance of the fire alarm system by a qualified person and provide written documentation to this office as proof of compliance.
 Email inspector documentation.

- INTERIOR EXITS MSFC 1030.2 Remove the materials that cause an exit obstruction. Maintain a clear and unobstructed exit path.
 Several doors were sticking when trying to open. Assure that the doors open without any difficulty.
- REFRIGERATOR/FREEZER WAREHOUSE THROUGHOUT MSFC 3205.5 -Maximum permissible storage height and pile volume in high-piled storage areas shall be in accordance with MSFC table 3206.2 Maximum pile / volume shall not exceed 12 feet.
 -Multiple areas throughout the building had storage in excess of 12 feet, approximately 20 to 24 feet in some areas at the time of inspection. Reduce the storage height to no more than 12 feet off the ground.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8585) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: Sebastian.Migdal@ci.stpaul.mn.us or call me at 651-266-8985 between 8:00 a.m. - 9:30 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Sebastian Migdal Fire Safety Inspector

Reference Number 35410

1



240 Chester

NO 16



-14