

WORK PLAN - BREAKDOWN COST OF REHABILITATION
 (To be done in accordance with the Code Compliance Inspection Report) Address: 201 Geneva St.

WEEK OF	TASKS	CONTRACTOR	Supplies/Materials on hand (if any)	Needed Supplies/Materials	Owner/Developer Labor	Value of Cost
1/24 - 1-31	Garage - Removal of Mattress, ect			Possible Dumpster Rental	TBD	\$1,000 - 1,400
	Bathroom Caulking & Ceiling Patch			Seal Primer Dry wall, mud, tools	myself	TBD
	Back door Flashing - TBD if can complete due to weather					
	Fence - TBD if can do due to weather					
	Garage Service door Dead bolt - Completed			TBD	TBD	\$300
	Garage Door repair -					
	front Porch furniture garbage is completed				Tenant Tenant	

Total Project Cost: \$ TBD

Note: (Code Enforcement Officers estimate the cost to repair this structure is \$ _____ to \$ _____).