


621 Bidwell St Front View 9-17-23



broken gall, small debris in drive

621 Bidwell St Front View 9-17-23



< 6 or so volunteer trees to left significantly enmeshed with power lines






Setback area between 621 Bidwell St and neighboring property to the south, 133 Baker St W



volunteer trees along south edge of driveway & power line





sideyard in the north of  
621 Bidwell St property



sideyard in the north of  
621 Bidwell St property





sideyard in the north of  
621 Bidwell St property



< feces dropped from above  
down fence into property,  
likely from 140 King St W  
(adjacent property on other  
side of fence)

sideyard in the north of  
621 Bidwell St property