












Date:	July 26, 2023
File #:	22 - 121732
Folder Name:	986 GALTIER ST
PIN:	252923140137































































Date: File #: Folder Name: PIN:	July 26, 2023 22 - 121732 986 GALTIER ST 252923140137	
***This affic property. A c	CITY OF ST. PAUL DEPARTMENT OF SAFETY AND INSPECTIONS 375 JACKSON STREET, SUITE 220 SAINT PAUL, MINNESOTA 55101-1806 Phone: 651-266-8989 Fax: 651-266-8951 Visit our Web Site at www.stpaul.gov/dsi	SINGLE FAMILY OR DUPLEX SMOKE & CARBON MONOXIDE DETECTOR INSPECTION AFFIDAVIT Revised 04/2020 inspector upon inspection of the ed without this completed affidavit. ***
Single family	repupier <u>786 Gattier</u> S Addre	H. Saint Paul New 55
 The location Instruction The process Who to construct the penaltic 	, the owner, or responsible party has given the address a written explanation of the following on and operation of each smoke detector and as describing the action to be taken when an a dures for testing the detectors. Intact when a low-battery tone sounds or pow ies for disabling smoke detection or carbon or result in a criminal citation.	: carbon monoxide detector. alarm sounds. ver light fails.
monoxide detect	te owner, or responsible party has inspect fors in the single family or duplex at the a place and in good working order.	ted the smoke detectors and carbon above address and that all required
mature:	2	Date: 7/17/2023
nnesota State S	Statute 299F.362 requires smoke deter	ctors and Minnesota State Statute 299

Minnesota State Statute 299F.362 requires smoke detectors and Minnesota State Statute 299 requires carbon monoxide detectors. Saint Paul Ordinance 39.02(c) requires that an affidavit s hat "all detectors are inspected and serviced when needed and are operational be filed be Certificate of Occupancy can be issued or renewed."