

WORK PLAN - BREAKDOWN COST OF REHABILITATION

(To be done in accordance with the Code Compliance Inspection Report) Address: _____

WEEK OF	TASKS	CONTRACTOR	Supplies/Materials on hand (if any)	Needed Supplies/Materials	Owner/Developer Labor	Value of Cost
4-24-23	bathroom	Aychoeum Te	tiles		Paid	1,500
4-30-23	kitchen	Oudam Tum Te	full cabinet		Paid	2,500
			stove		Paid	1050
			refrigerator		Paid	540
4-24-23	framing door and window lock		framing	have all		
	Heat	Turn on Heat				
4-24-23	door					
	garage	Aychoeum Te	trim			
	house		paint		Paid	300
	-in house	Aychoeum Te	paint		Paid	30
	(install flooring than hund cabinet thank		floor vinyl			

Heat will install the stove by heating.

Total Project Cost: \$ _____

Note: (Code Enforcement Officers estimate the cost to repair this structure is \$ _____ to \$ _____).