



CITY OF SAINT PAUL

375 Jackson Street, Suite 220  
Saint Paul, Minnesota 55101-1806

Telephone: 651-266-8989  
Facsimile: 651-266-8951  
Web: [www.stpaul.gov/dsi](http://www.stpaul.gov/dsi)

May 20, 2021  
CAROLYN BROWN  
COMMUNITY STABILIZATION PROJECT  
501 DALE STREET N APT. 203  
SAINT PAUL MN 55103

**NOTICE OF CONDEMNATION  
UNFIT FOR HUMAN HABITATION  
ORDER TO VACATE**

RE: 140 ISABEL ST E  
Ref. # 107292

Dear Property Representative:

Your building was inspected on May 20, 2021.

The building was found to be unsafe, unfit for human habitation, a public nuisance, a hazard to the public welfare or otherwise dangerous to human life. A Condemnation Placard has been posted on the building.

The following deficiency list must be completed or the building vacated by the re-inspection date.

A reinspection will be made on or after June 21, 2021.

**CONDEMNATION OF THE BUILDING REVOKES THE CERTIFICATE OF OCCUPANCY.**

Failure to complete the corrections may result in a criminal citation. The Saint Paul Legislative Code requires that no building be occupied without a Fire Certificate of Occupancy.

**DEFICIENCY LIST**

1. Throughout - SPLC 34.23, MSFC 110.1 - This occupancy is condemned as unsafe or dangerous. This occupancy must not be used until re-inspected and approved by this office.  
-This property is condemned due to, but not limited to, extensive exterior repairs including holes in the roof and an unsafe front porch.

2. Exterior - SPLC 34.09 (2), 34.33 (1) - Provide and maintained the roof weather tight and free from defects.  
-Gutter coming off of damaged roof on the front.  
-West of the property has a tarp covering the roof.
3. Exterior - SPLC 34.08 (1), 34.32 (1) - All exterior property areas shall be maintained free from any accumulation of refuse, garbage or feces.  
-Trash and mattresses throughout the exterior.
4. Exterior - SPLC 34.09 (3), 34.33(2) - Repair or replace the unsafe stairways, porch, decks or railings in an approved manner. This work may require a permit(s). Call DSI at (651) 266-8989.  
-Front porch has multiple loose and rotting spots.
5. Exterior - SPLC 34.08 (10) - Repair, replace and maintain exterior sidewalks, walkways and stairs.  
-Concrete stairs are deteriorated.
6. See Comments - SPLC 34.19 - Provide access to the inspector to all areas of the building.
7. SPLC 39.02(c) - Complete and sign the smoke detector affidavit and return it to this office.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: <http://www.stpaul.gov/cofo>

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8585) and must be filed within 10 days of the date of the original orders.

If you have any questions, email me at: [adam.powers@ci.stpaul.mn.us](mailto:adam.powers@ci.stpaul.mn.us) or call me at 651-266-8982 between 7:30 - 9:00 a.m. Please help make Saint Paul a safer place in which to live and work.

Sincerely,

Adam Powers  
Fire Safety Inspector  
Ref. # 107292

cc: Housing Resource Center  
Force Unit