

## Ashli Jones

---

**From:** no-reply@ci.stpaul.mn.us  
**Sent:** Wednesday, January 24, 2024 8:20 PM  
**To:** #CI-StPaul\_Form4  
**Subject:** Inspection Request

The following inspection request was submitted on 24 Jan 2024 20:20:

Owner Name: NICOLAS RESENDIZ CECILIA RESENDIZ  
Address: 1056 BEECH ST  
-----

Property Type: single-family

No Heat: on

Situation Description: This is a vacant house and family members checked on it today and found that the heat was not working and a water pipe had burst. Water had leaked over the furnace and it was not operational. The gas was shut off at the meter and Xcel was requested to ensure it was safe to turn the gas back on. Please complete an inspection to ensure the house is safe.

Name: Andrew Vorlicek  
Rank: FDC  
Company: D3B