SPRWS Work Related Injuries April-June 2019

SPRWS Claim #	Date of Injury	Division	Job Title	Injury Description	Body Part
<u>19-0014</u>	4/18/2019	Distribution	WATER UTILITY WORKER II	Employee was working on a lead replacement and stepped on broken sidewalk and rolled left ankle.	Sprained Left Ankle
<u>19-0015</u>	4/1/2019	Production	WATER PLANT WORKER	Employee is having reoccurrence of carpel tunnel in left hand and wrist due to the repetition of pushing and squeezing duties in his job.	Left Hand & Wrist
<u>19-0016</u>	4/20/2019	Production	PAINTER	Employee was taking out a steel door frame with a cutting wheel and a piece of steel flew into his right eye.	Right Eye
19-0017	5/16/2019	Distribution	WATER UTILITY WORKER I	Employee was putting some tools away in the back of the work truck and got his right middle finger pinched between the tailgate and truck.	Right middle finger
<u>19-0018</u>	5/9/2019	Distribution	WATER UTILITY WORKER I	Employee walked into the edge of the tailgate with his right side. No medical attention sought.	Right side
<u>19-0019</u>	5/21/2019	Production	UTILITY AIDE	Employee was mowing grass on a hill and while attempting to keep the mower from rolling down the hill, pulled shoulders/back/neck.	Shoulders, lower back and neck
<u>19-0020</u>	5/23/2019	Production	UTILITY AIDE	Employee noticed a round bruise with a hard spot in the middle on 5/23. It was still there on 5/29 so they went in to get it checked for a possible tick bite.	Right Forearm
19-0021	6/3/2019	Production	MAINTENANCE WORKER	Employee was at the Mailand Pumping Station and slipped and fell, jamming his left finger. No medical attention sought.	Left Finger
<u>19-0022</u>	6/20/2019	Engineering	CAPITAL CITY INTERN	Employee was at a mains construction project and tripped over some materials that were on the ground. They fell and got a small cut. First aid treatment only.	Right ankle