

Moermond, Marcia (CI-StPaul)

From: Martin, Lisa (CI-StPaul)
Sent: Wednesday, August 23, 2017 7:27 AM
To: Moermond, Marcia (CI-StPaul)
Cc: derickson@levander.com
Subject: 1440 Albert
Attachments: IMG_0619.jpg; IMG_0620.jpg; IMG_0621.jpg; IMG_0622.jpg; IMG_0623.jpg; IMG_0625.jpg; IMG_0626.jpg

There is no access to the rear door, and small path to the front door. No access to an egress window in Jeanette's room. The hallway between the two bathrooms needs to be clear. There is a photo of a chair that the owner states Jeanette sits in often. I am concerned of the tripping hazards, and no access to many exits. Bob wanted me to take a photo of the basement stairs as he feels in an emergency they can get out from the basement. The basement is not an option for an exit at this time. I contacted Lauren at House Calls to inform her that the kitchen looks great, but we need exits open. I can re-inspect on Thursday at 1:30pm.

Thanks!



Lisa Martin

Inspector III/Code Enforcement Division

Department of Safety and Inspections

375 Jackson St, Suite 220

Saint Paul, MN 55101-1806

P: 651-266-1940

lisa.martin@ci.st.paul.mn.us

“DSI’s Mission: To preserve and improve the quality of life in Saint Paul by protecting and promoting public health and safety for all.”