

Saint Paul Department of Planning and Economic Development Historic Review Form

Please type or print legibly. (Illegible forms v	will be returned.)			
Project Address: 871 JESSAMINE AVE E	Original Construction Year:		1951	
Building Name:			5	
Brief Project Description: Removal of Nuisance Building				
*				
Funding: CDBG X NSPII Other Funding (list)				
Form Completed by: Rich Singerhouse / Tom Friel		Date:	April 1, 2019	
Title/Organization: DSI Supervisor/Inspector	Phone no:	551-266-194	45/1906	
Reviews will not be processed with Photo of building a Map clearly showing loc	attached below		*	
Completed review will be returned to this address: Form submitted by: City of Saint Paul, Planning and Econo	omic Development	(PED)		
Contact Person: Bill Dermody, City Planner (651-266	6-6617)		e e e e e e e e e e e e e e e e e e e	
Street Address: 1400 City Hall Annex, 25 W. Fourth St	t., Saint Paul, MN 5	55102		-
Please complete Historic Review form for each address and send Fourth Street, Saint Paul, MN 55102	to Samantha Langer	, 1400 City I	Hall Annex, 25 W.	
Name: Smartha Langer Add Add Add Add Add Add Add A	lditional Comments:			
Date: 4-22-19		×		-
This project has been reviewed by the Minnesota Preservation Act (36CFR800), the Minnesota Farchaeology Act, as applicable. There are no report project area, and we feel that the probability of any on available information, we conclude that no hational Register of Historic Places will be affect contact the Environmental Review staff at (651) 201 Sarah Beimers Manager, Environmental Review Program	Historic Sites Accorted historic or a unreported properties ed by this project -3286.	t, and the chaeologic erties is low eligible for	e Minnesota Fiel cal resources in the v. Therefore, base or or listed on the nave any question	d e d e