

□ Other

APPLICATION FOR APPEAL

RECEIVED
OCT 0 4 2010

CITY CLERK

Saint Paul City Clerk

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8560

| | g . | |
|-------------------------------------------------------------|-----------------|-------------------------------|
| The City Clerk needs the following to pro | | YOUR HEARING Date and Time: |
| (if cash: receipt number) | | Tuesday, Vet. 12 |
| Copy of the City-issued orders or letter are being appealed | which | Time1'30 |
| Attachments you may wish to include | | Location of Hearing: |
| This appeal form completed | | Room 330 City Hall/Courthouse |
| A TEST TOWN B A TE | | |
| Address Being Appealed | | |
| Number & Street: 1337 Port | | |
| Appellant/Applicant: Teri Bretm | Len | ail bretonfam@comcast.ne |
| Phone Numbers: Business | Residence 651-6 | 45-1025 Cell |
| | | Date: 9/27/2010 |
| Name of Owner (if other than Appellant): | Marc + their | reser Breton |
| Address (if not Appellant's): 1331 Po | r-Hand Ave, | St. Paul, MN 55104 |
| Phone Numbers: Business | Residence 651-6 | 45-1025 Cell |
| What Is Being appealed | and why? | Attachmento Ana Accoutable |
| What is being appeared | and viry. | Attuchments Are Acceptable |
| Vacate Order/Condemnation/ Revocation of Fire C of O | | · |
| □ Summary/Vehicle Abatement | | |
| Fire C of O Deficiency List | | \$ " |
| ☐ Fire C of O: Only Egress Windows | | |
| □ Code Enforcement Correction Notice | Ce Vo | |
| □ Vacant Building Registration | 0 0 | |
| □ Other | | |
| □ Other | | |

Marc and Theresa Breton

1331 Portland Avenue • St. Paul, MN 55104 • 651-645-1025 • bretonfam@comcast.net

September 29, 2010

St. Paul City Clerk 310 City Hall 15 W. Kellogg Blvd. St. Paul, MN 55102

Re:

Fire Inspection Correction Notice, Reference #113390

Duplex at 1337 Portland Avenue, St. Paul, MN 55104

To whom it may concern:

In the "Fire Inspection Correction Notice" we received dated 9/24/2010, eleven deficiencies were noted. We are appealing deficiencies (6) and (10):

Deficiency (6): Bedrooms MSFC1026.1 – Provide and maintain approved escape window from each sleeping room...with a minimum of 24 inches of openable height and 20 inches of openable width.

Four windows are identified in this deficiency, two that open to 23" and two that open to 20.5". Openable width is 27" for all 4 windows.

Basis of appeal: The 24"x20" opening requirement is 480 square-inches. Two of these windows have a 621 square inch opening (30% more than required) and two have a 553 square inch opening (15% more than required). There is an extra 7" of width in all cases, which more than compensates for the missing 1" to 3.5" in height. I am certain that a firefighter or tenant could enter or exit from these windows more easily than they could from a 24"x20" window.

Deficiency (10): SPLC34.11(6) and 34.34(3)... Submit a copy of the St. Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.

<u>Basis of appeal</u>: The two boilers in this duplex are brand new, installed less than a year ago on 10/29/2010. They were tested and approved by a St. Paul City permit inspector within the last 6 months. We also have a gas leak tester that indicates no leaks.

Thank you for your attention to this matter,

Teri Breton

cc: Rick Gavin, City of St. Paul Fire Inspector

375 Jackson Street, Suite 220



CITY OF SAINT PAUL Christopher B. Coleman, Mayor

weeken Se Saint Paul, Minnesota 55101-1806

Telephone: 651-266-8989 r Facsimile: 651-266-8951

Web: www.stpaul.gov/dsi

September 24, 2010

MARC BRETON THERESA BRETON 1331 PORTLAND AVE ST PAUL MN 55104-6906 Pts for deliciencies web: www.stpaul.govasi

Pts for deliciencies For Selfs

Selfs

Syls

Class A - 25,615, 1988

Class A - 7111 pts.

FIRE INSPECTION CORRECTION NOTICE

RE:

1337 PORTLAND AVE

Ref. #113390

Residential Class: C

Dear Property Representative:

Your building was inspected on September 24, 2010 for the renewal of your Fire Certificate of Occupancy. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected prior to the re-inspection date. A reinspection will be made on October 27, 2010 at 1:00 PM.

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

YOU WILL BE RESPONSIBLE FOR NOTIFYING TENANTS IF ANY OF THE FOLLOWING LIST OF DEFICIENCIES ARE THEIR RESPONSIBILITY.

DEFICIENCY LIST

- Basement SPLC 34.10 (5), 34.33 (4), 34.16 Provide and maintain interior in a clean 1. and sanitary condition.-Reduce storage by 20 percent. Remove unused gas stove.
- 2. Basement - UMC 504.6 - Provide, repair or replace the dryer exhaust duct. Exhaust ducts for domestic clothes dryers shall be constructed of metal and shall have a smooth interior finish. The exhaust duct shall be a minimum nominal size of four inches (102 mm) in diameter. This work may require a permit(s). Call DSI at (651) 266-8989.
- 3. Basement - SPLC 34.10 (3), 34.33(2) - Repair or replace the unsafe stairway in an approved manner.-Remove or replace damaged floor coverings that are a tripping hazard. An Equal Opportunity Employer

- 4. Bathroom Lower level SPLC 34.11, SBC 2902.1, SPLC 34.17, MPC 415.0220 Repair or replace and maintain the plumbing fixture to an operational condition.-Repair or replace and maintain an approved private tub or shower. Provide an approved shower handle.
- 5. Bathroom Lower level SPLC 34.10 (7), 34.33 (6) Repair and maintain the walls in an approved manner.-Scrape and remove chipped and peeling paint. Repaint in a professional manner.
- 6. Bedrooms MSFC1026.1 Provide and maintain an approved escape window from each sleeping room. The minimum size must be 5 square feet of glazed area with a minimum of 24 inches of openable height and 20 inches of openable width. With a finished sill height not more than 48 inches. This work may require permit(s). Call DSI at (651)-266-9090. Refer to the Escape Windows for Residential Occupanices handout for more information.-

Lower level Southeast
23 h x 27 w Glazed 7.7 sq ft
Lower level Northwest
23 h x 27 w Glazed 7.7 sq
Upper level South
20.5 h x 27 w Glazed 7.7 sq ft
Upper level North
20.5 h x 27 w Glazed 7.7 sq ft

- 7. Lower level Refrigerator NEC 440.13 For cord-connected equipment such as room air conditioners, household refrigerators and freezers, drinking water coolers, and beverage dispensers, a separable connector or an attachment plug and receptacle shall be permitted to serve as the disconnecting means. The appliance must plug directly into a permanent outlet.
- 8. South bedroom Lower level MSFC 1011.2 Remove the materials that cause an exit obstruction. Maintain a clear and unobstructed exitway.
- 9. Throughout MSFC 605.4 Discontinue use of all multi-plug adapters.
- 10. SPLC 34.11 (6), 34.34 (3) Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.
- 11. SPLC 39.02(c) Complete and sign the provided smoke detector affidavit and return it to this office.

For an explanation or information on some of the violations contained in this report, please visit our web page at: http://www.ci.stpaul.mn.us/index.aspx?NID=211

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8688) and must be filed within 10 days of the date of this order.

\$25 x

If you have any questions, email me at: rick.gavin@ci.stpaul.mn.us or call me at 651-266-8994 between 7:30 a.m. - 9:00 a.m. Please help to make Saint Paul a safer place in rease h which to live and work.

Sincerely,

Rick Gavin Fire Inspector

Reference Number 113390