

Date: April 30, 2013
File #: 13 - 179908
Folder Name: 106 KING ST E
PIN: 082822240067

HP District:
Property Name: house
Survey Info: RA-SPC-4092



East side, posting



South and west sides



North side



Front posting



Rear posting



Water damaged ceiling

Date: April 30, 2013
File #: 13 - 179908
Folder Name: 106 KING ST E
PIN: 082822240067

HP District:
Property Name: house
Survey Info: RA-SPC-4092



Water damaged wall



Water damaged ceiling




Water damaged wall



Water damaged walls



Water damaged wall



Unapproved hand rail

Date: April 30, 2013
File #: 13 - 179908
Folder Name: 106 KING ST E
PIN: 082822240067

HP District:
Property Name: house
Survey Info: RA-SPC-4092



Rear posting



Rear posting



Deteriorated masonry



Rot damaged siding



Deteriorated masonry



Front posting

Date: April 30, 2013
File #: 13 - 179908
Folder Name: 106 KING ST E
PIN: 082822240067

HP District:
Property Name: house
Survey Info: RA-SPC-4092



Rodent feces



Stove



Water damaged ceiling