



Front upper windows



Front upper windows



Front upper windows



North side lower windows
- Tape still needs to be removed
from painting



South Wall upper level.



North side of building