

Moermond, Marcia (CI-StPaul)

From: Wiese, Angie (CI-StPaul)
Sent: Monday, January 13, 2014 3:24 PM
To: Moermond, Marcia (CI-StPaul)
Cc: Neis, Adrian (CI-StPaul); Shaff, Leanna (CI-StPaul); Owens, Phil (CI-StPaul); Spiering, Wayne (CI-StPaul)
Subject: FW: 2441 Univ W
Attachments: 2441 With Photo Descriptions.doc

Marcia,

Please see comments below from Mike Barck and the attached photos (with photo description) for 2441 University Ave W.

Let me know if you need anything else,

Angie Wiese, PE, CBO
Safety & Inspections
651-266-8953

From: Barck, Mike (CI-StPaul)
Sent: Tuesday, January 07, 2014 11:01 AM
To: Wiese, Angie (CI-StPaul)
Subject: 2441 Univ W

Angie,

Two items were apparent to me regarding the inspection that I attended with you and Wayne Spiering yesterday at 2441 University Ave West.

Item 1 - The wooden loading dock at the North end of the building appears to lack legitimate frost footings as well as adequate structural elements.

Item 2 - The stair toward the rear of the building connects 4 floors which would require the stairs to be within a 1HR enclosure. Currently there are no fire rated doors assemblies nor walls at any of the levels that the stair serves.



Mike Barck

Building Inspector

Department of Safety and Inspections

375 Jackson St, Suite 220

Saint Paul, MN 55102

P: 651-266-9029

mike.barck@ci.stpaul.mn.us

The Most Livable
City in America

facebook

YouTube

twitter



Making Saint Paul the Most Livable City in America