

APPLICATION FOR APPEAL

Saint Paul City Council - Legislative Hearings

RECEIVED Saint Paul Missesses Telephone: (651) 266-8585

SEP 25 2015

We need the following to process your appeal:	CLERK
\$25 filing fee (non-refundable) (payable to the City of Saint Pau	
(if cash: receipt number Check 3080)	(provided by Legislative Hearing Office)
Copy of the City-issued orders/letter being appealed	Tuesday, 10 - 6 - 15
 Attachments you may wish to include This appeal form completed 	Time_1!30 PM
,	Location of Hearing:
₩ Walk-In OR □ Mail-In	Room 330 City Hall/Courthouse
for abatement orders only: Email OR Fax	,
Address Being Appealed:	
Number & Street: 633 PACACE City:	Sr. Paur State: Mw Zip: 5510 Z
Appellant/Applicant: Row Staehel! E	imail Rone GMail.com
Phone Numbers: Business 612-865-2004 Residence 65	1-295-0100 Cell
Signature:	Date:
Name of Owner (if other than Appellant):	
Mailing Address if Not Appellant's:	
Phone Numbers: Business Residence	Cell
What Is Roing Annualed and What?	
What Is Being Appealed and Why?	Attachments Are Acceptable
Vacate Order/Condemnation/ Revocation of Fire C of O	
□ Summary/Vehicle Abatement	
VE: 0.10 D.11.1. 11.10	
Fire C of O Deficiency List/Correction INCONFECT	//
□ Code Enforcement Correction Notice	orders, vauge, no co Bullday
□ Code Enforcement Correction Notice □ Vacant Building Registration	orders, vauge, no co Bullday



CITY OF SAINT PAUL

Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Telephone: 651-266-8989 Saint Paul, MN 55101-1806 Fax: 651-266-8951

September 16, 2015

RON STAEHELI 633 PALACE AVE. ST PAUL MN 55102 USA

CORRECTION NOTICE - COMPLAINT INSPECTION

RE:

633 PALACE AVE

Ref. # 122263

Dear Property Representative:

An inspection was made of your building on April 1, 2015 in response to a referral. You are hereby notified that the following deficiency list must be corrected immediately.

A reinspection will be made on October 7, 2015 at 10:00am.

Failure to comply may result in a criminal citation. The code also provides for the assessment of additional reinspection fees.

DEFICIENCY LIST

- 1. SPLC 34.19 Provide the inspector access to the building. –Allow access to verify all of the corrections have been made
- 2. EXTERIOR GARAGE SPLC 34.08(5), 34.32(3) All accessory structures including, but not limited to, detached garages, sheds and fences shall be maintained structurally sound and in good repair. Provide and maintain exterior unprotected surfaces painted or protected from the elements. -Scrape and paint where needed.
- 3. EXTERIOR ROOF SPLC 34.09 (1) e, 34.32 (1) d Provide and maintained the roof weather tight and free from defects. Shingles are deteriorated.
- 4. EXTERIOR SPLC 34.09 (1) b,c, 34.33 (1) b, c Provide and maintain all exterior walls free from holes and deterioration. All wood exterior unprotected surfaces must be painted or protected from the elements and maintained in a professional manner free from chipped or peeling paint. -Scrape and paint where needed. -Areas of siding and window sill with missing/peeling paint.
- 5. EXTERIOR SPLC 34.09 (3), 34.33 (3) -Provide or repair and maintain the window screens, where damaged, broken, or missing.

- 6. INTERIOR MAIN HALLWAY MSFC 605.1 Remove unapproved exposed wiring and install in accordance with the electrical code. This work may require a permit(s). Call DSI at (651) 266-9090. -Exposed electrical in the closet.
- 7. INTERIOR MAIN HALLWAY NEC 110-26 Provide and maintain a minimum of 36 inches clearance in front of all electrical panels.-Remove the storage blocking the electrical panel.
- 8. INTERIOR MAIN HALLWAY SPLC 34.10 (7), 34.34 (6) Repair and maintain the walls in an approved manner. -Cracked, damaged, and missing plaster.
- 9. UPPER UNIT SPLC 34.09 (3), 34.32 (3) Repair and maintain the window in good condition. Some windows are difficult to open and will pull away from there frames. Some windows will not stay in the openable position.
- 10. UPPER UNIT SPIC 34.14 (3), MPC 4715.200.T Provide and maintain a window or approved ventilation system in all bathrooms. -Bathroom fan was illegally and improperly installed without permits and is not properly vented. This work will require a permit. Contact DSI at 651-266-8989.
- 11. UPPER UNIT SPLC 34.11, MSBC 2902.1, SPLC 34.17, MSPC 415.0220 Repair or replace and maintain all parts of the plumbing system to an operational condition. Repair or replace and maintain an approved private hand sink. This work may require a permit(s). Call DSI at (651) 266-8989. -Hand sink outside the bathroom was installed without permits.
- 12. UPPER UNIT MN State Statute 299F.50 Immediately provide and maintain an approved Carbon Monoxide Alarm in a location within ten (10) feet of each sleeping area. Installation shall be in accordance with manufacturer's instructions.-
- 13. UPPER UNIT DRYER MSFC 605.5 Discontinue use of extension cords used in lieu of permanent wiring. -Gas dryer is connected and an extension cord through a doorway was in use.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8585) and must be filed within 10 days of the date of the original orders.

If you have any questions, email me at: adrian.neis@ci.stpaul.mn.us or call me at 651-266-8992 between 7:30 a.m. - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

A.J. Neis Fire Inspector

Ref. # 122263

CC: Therese Skarda, City Attorney's Office