Service Order #	Type of Service Order	Service Message	Print Date	Date Work Completed	Date/Time Created	Date/Time Printed	Work Done By	Completed Timestamp
695507	1	PLEASE GET A READING TO CHECK IF USAGE HAS GONE DOWN AFTER SPRWS	10/3/2024	10/3/2024	10/3/2024 3:41:19 AM		Joel	10/4/2024 8:12:02 AM
	(MTR OPS ONLY)	CONTACTED CUSTOMER ABOUT HIGH USE					Koppendrayer	
694642	LEAK AUDIT PROGRAM		9/26/2024	9/26/2024	9/26/2024 7:06:59 AM	1 '	JOSEPH	I 9/26/2024 7:07:09 AMI
				9/20/2024		1	TRONSON	
661256		PLEASE VERIFY METER/REGISTER INFORMATION ~	,			1		(
	METER INVESTIGATION	(LAURA SEVERSON 815-276-1381)	8/7/2023		8/7/2023 8:59:09 AM	()		'
		CHECK PROPERTY SERVICE MATERIAL Recorded Material: Copper						
553578	CONNECT NEW	TO NEW ~ 1" (PERMIT - 1") ~ OPEN / JIM	8/21/2019	8/22/2019	8/21/2019 12:21:38 PM		NATHAN PEARL	8/22/2019 3:48:28 PM
	1							