

Account #: 9900158385


Order #: 1195745

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Case #: 703271-9209909



Date Completed:  
before: replace window screens



Date Completed:  
before: replace window screens entryway



Date Completed:  
before: replace window screens entryway




Date Completed:  
before: replace window screens upstairs

Account #: 9900158385

Order #: 1195745

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Case #: 703271-9209909



Date Completed:

before: replace window screens upstairs



Date Completed:

before: replace window screens upstairs



Date Completed:

before: replace window screens upstairs



Date Completed:

before: replace window screens upstairs



Account #: 9900158385

Order #: 1195745

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Case #: 703271-9209909



Date Completed:

before: replace window screens upstairs



Date Completed:

before: replace window screens upstairs



Date Completed:

before: replace window screens upstairs



Date Completed:

before: replace waste piping



Account #: 9900158385


Order #: 1195745

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Case #: 703271-9209909



Date Completed:  
before: rewire



Date Completed:  
before: rewire



Date Completed:  
before: rewire



Date Completed:  
before: rewire



Account #: 9900158385


Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Order #: 1195745

Case #: 703271-9209909



Date Completed:  
before: rewire



Date Completed:  
before: rewire



Date Completed:  
before: rewire



Date Completed:  
before: rewire



Account #: 9900158385

Order #: 1195745

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106


Case #: 703271-9209909



Date Completed:  
before: rewire



Date Completed:  
before: rewire



Date Completed:  
before: rewire



Date Completed:  
before: rewire



Account #: 9900158385

Order #: 1195745

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106


Case #: 703271-9209909



Date Completed:  
before: rewire



Date Completed:  
before: rewire



Date Completed:  
before: rewire



Date Completed:  
before: rewire




Account #: 9900158385

Order #: 1195745

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106


Case #: 703271-9209909




Date Completed:  
before: rewire



Date Completed:  
before: rewire hazardous wire in basement



Date Completed:  
before: rewiring



Date Completed:  
before: rn condensate drain



Account #: 9900158385

Order #: 1195745


Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Case #: 703271-9209909




Date Completed:

before: upgrade circuit to nec standard



Date Completed:

before: vent clotting dryer to code



Date Completed:

before: repair/pressure wash stucco



Date Completed:

before: repair/replace window sash upstairs kitchen



Account #: 9900158385

Order #: 1195745

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Case #: 703271-9209909



Date Completed:  
before:replace



Date Completed:  
before:rewire to standard attic



Date Completed:  
before; refinish wood floor livingroom



Date Completed:  
befroe: prep&paint exterior trim



Account #: 9900158385

Order #: 1195745

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Case #: 703271-9209909



Date Completed:

brfore:insulate attic access door



Account #: 9900158385

Order #: 1195745


Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Case #: 703271-9209909



Date Completed:

condition



Date Completed:

condition



Date Completed:

condition



Date Completed:

condition



Account #: 9900158385

Order #: 1195745

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Case #: 703271-9209909



Date Completed:

condition



Date Completed:

condition



Date Completed:

condition



Date Completed:

condition




Account #: 9900158385

Order #: 1195745

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Case #: 703271-9209909



Date Completed:

condition



Date Completed:

condition



Date Completed:

condition



Date Completed:

condition



Account #: 9900158385

Order #: 1195745


Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Case #: 703271-9209909



Date Completed:

condition



Date Completed:

condition



Date Completed:

condition



Date Completed:

condition



Account #: 9900158385

Order #: 1195745

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Case #: 703271-9209909




Date Completed:

condition



Date Completed:

condition



Date Completed:

condition



Date Completed:

condition



Account #: 9900158385

Order #: 1195745


Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Case #: 703271-9209909



Date Completed:

condition



Date Completed:

condition



Date Completed:

condition



Date Completed:

before condition



Account #: 9900158385

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Order #: 1195745

Case #: 703271-9209909



Date Completed:  
before install fire rated entry doors



Date Completed:  
before install furnace filter



Date Completed:  
before insulate attic floor



Date Completed:  
before level garage floor



Account #: 9900158385


Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Order #: 1195745


Case #: 703271-9209909



Date Completed:  
before level garage floor



Date Completed:  
before provide complete circuit directory



Date Completed:  
before replace window screens upstairs



Date Completed:  
before replace window screens upstairs



Account #: 9900158385

Order #: 1195745

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Case #: 703271-9209909



Date Completed:  
before"repair/pressure wash stucco



Date Completed:  
before:



Date Completed:  
before:



Date Completed:  
before: bond water meter



Account #: 9900158385

Order #: 1195745

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106


Case #: 703271-9209909



Date Completed:  
before: bond water meter



Date Completed:  
before: circuit breaker amp



Date Completed:  
before: circuit breaker amp



Date Completed:  
before: circuit breaker amp




Account #: 9900158385


Order #: 1195745

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Case #: 703271-9209909



Date Completed:  
before: circuit breaker amp



Date Completed:  
before: circuit breaker rewiring



Date Completed:  
before: clean kitchen floor carpet



Date Completed:  
before: clean kitchen floor carpet



Account #: 9900158385


Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Order #: 1195745

Case #: 703271-9209909



Date Completed:  
before: clean kitchen floor carpet



Date Completed:  
before: corroded cast iron



Date Completed:  
before: cover water pit with concrete



Date Completed:  
before: cover water pit with concrete



Account #: 9900158385

Order #: 1195745

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Case #: 703271-9209909



Date Completed:

before: cover water pit with concrete



Date Completed:

before: cracks/loose plaster diningroom



Date Completed:

before: cracks/loose plaster diningroom



Date Completed:

before: ereplace cast iron




Account #: 9900158385

Order #: 1195745

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Case #: 703271-9209909



Date Completed:  
before: gorund electric service



Date Completed:  
before: grade land scape



Date Completed:  
before: grade landscape



Date Completed:  
before: grade landscape



Account #: 9900158385

Order #: 1195745

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106


Case #: 703271-9209909




Date Completed:  
before: grade landscape



Date Completed:  
before: grade landscape



Date Completed:  
before: ground electric service



Date Completed:  
before: ground electric service



Account #: 9900158385


Order #: 1195745

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Case #: 703271-9209909




Date Completed:  
before: install bgarage circuit



Date Completed:  
before: install chimney liner



Date Completed:  
before: install down spouts



Date Completed:  
before: install down spouts



Account #: 9900158385

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Order #: 1195745

Case #: 703271-9209909



Date Completed:  
before: install down spouts



Date Completed:  
before: install down spouts



Date Completed:  
before: install fire rated entry doors



Date Completed:  
before: install fire rated entry doors



Account #: 9900158385

Order #: 1195745

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Case #: 703271-9209909



Date Completed:  
before: install fire rated entry doors



Date Completed:  
before: install fire rated entry doors



Date Completed:  
before: install fire rated entry doors



Date Completed:  
before: install fire rated entry doors



Account #: 9900158385

Order #: 1195745

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Case #: 703271-9209909



Date Completed:  
before: install fire rated entry doors



Date Completed:  
before: install fire rated entry doors



Date Completed:  
before: install garage circuit



Date Completed:  
before: install garage door opener receptacle




Account #: 9900158385

Order #: 1195745

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Case #: 703271-9209909




Date Completed:

before: install garage door opener receptacle



Date Completed:

before: install garage door receptacle



Date Completed:

before: install glass block upstairs bathroom window



Date Completed:

before: install glassblock window in upstairs bath



Account #: 9900158385


Order #: 1195745

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Case #: 703271-9209909




Date Completed:  
before: install gutters



Date Completed:  
before: install gutters



Date Completed:  
before: install gutters



Date Completed:  
before: install gutters



Account #: 9900158385

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Order #: 1195745

Case #: 703271-9209909




Date Completed:  
before: install gutters



Date Completed:  
before: install gutters



Date Completed:  
before: install gutters



Date Completed:  
before: install gutters and down spouts




Account #: 9900158385

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Order #: 1195745

Case #: 703271-9209909




Date Completed:  
before: install gutters/down spouts



Date Completed:  
before: install handrail in entryway



Date Completed:  
before: install handrail in entryway



Date Completed:  
before: install handrail in entryway




Account #: 9900158385

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Order #: 1195745

Case #: 703271-9209909




Date Completed:  
before: install handrail in entryway



Date Completed:  
before: install handrail in entryway



Date Completed:  
before: install handrail in entryway



Date Completed:  
before: install hard wire



Account #: 9900158385

Order #: 1195745

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Case #: 703271-9209909



Date Completed:  
before: install light fixture



Date Completed:  
before: install light fixture



Date Completed:  
before: install new handrail in entry way



Date Completed:  
before: install rain leaders



Account #: 9900158385

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Order #: 1195745

Case #: 703271-9209909



Date Completed:

before: install receptacle for garage door opener




Date Completed:

before: install receptacle for garage door opener



Date Completed:

before: install safety cable garage



Date Completed:

before: install safety cable garage



Account #: 9900158385

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106


Order #: 1195745

Case #: 703271-9209909



Date Completed:

before: install safety cable garage door




Date Completed:

before: install safety cable garage door



Date Completed:

before: install shut off valve



Date Completed:

before: install smoke dectector



Account #: 9900158385

Order #: 1195745

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Case #: 703271-9209909



08/17/12  
12:00:00 PM

Date Completed:  
before: install smoke dectector




08/17/12  
12:00:00 PM

Date Completed:  
before: install smoke dectector



08/17/12  
12:00:00 PM

Date Completed:  
before: install smoke dectector



08/17/12  
12:00:00 PM

Date Completed:  
before: install smoke dectector




Account #: 9900158385


Order #: 1195745

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Case #: 703271-9209909



Date Completed:  
before: install smoke detector



Date Completed:  
before: install smoke detector



Date Completed:  
before: install smoke detector



Date Completed:  
before: install smoke detector




Account #: 9900158385

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Order #: 1195745

Case #: 703271-9209909




Date Completed:  
before: install smoke detector



Date Completed:  
before: install vent fan bathroom



Date Completed:  
before: install vent fan bathroom



Date Completed:  
before: insulate attic access door



Account #: 9900158385

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Order #: 1195745

Case #: 703271-9209909




Date Completed:  
before: insulate attic floor



Date Completed:  
before: insulate attic floor



Date Completed:  
before: insulate attic floor



Date Completed:  
before: insulate attic floor



Account #: 9900158385

Order #: 1195745

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Case #: 703271-9209909




Date Completed:  
before: insulate attic floor



Date Completed:  
before: level garage floor



Date Completed:  
before: level garage floor



Date Completed:  
before: level garage floor



Account #: 9900158385

Order #: 1195745


Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Case #: 703271-9209909



Date Completed:

before: prep & paint exterior trim



Date Completed:

before: prep and mulch ground



Date Completed:

before: prep & mulch ground



Date Completed:

before: prep & mulch ground




Account #: 9900158385

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Order #: 1195745

Case #: 703271-9209909



Date Completed:  
before: prep& mulch ground



Date Completed:  
before: prep&mulch ground



Date Completed:  
before: prep&mulch ground



Date Completed:  
before: prep&paint ceiling upstairs



Account #: 9900158385

Order #: 1195745


Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Case #: 703271-9209909



Date Completed:

before: prep&paint ceiling upstairs



Date Completed:

before: prep&paint ceiling upstairs



Date Completed:

before: prep&paint exterior



Date Completed:

before: prep&paint exterior trim




Account #: 9900158385

Order #: 1195745

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Case #: 703271-9209909



Date Completed:  
before: prep&paint exterior trim



Date Completed:  
before: prep&paint exterior trim



Date Completed:  
before: prep&paint exterior trims



Date Completed:  
before: prep&paint exterior walls



Account #: 9900158385


Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Order #: 1195745

Case #: 703271-9209909



Date Completed:  
before: prep&paint exterior walls



Date Completed:  
before: prep&paint exterior walls



Date Completed:  
before: prep&paint interior ceiling



Date Completed:  
before: prep&paint interior walls




Account #: 9900158385

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Order #: 1195745

Case #: 703271-9209909




Date Completed:

before: prep&paint interior walls/ceiling




Date Completed:

before: prep&paint interior walls/ceiling



Date Completed:

before: prep&paint interior walls/ceiling



Date Completed:

before: prep&paint interior walls/ceiling




Account #: 9900158385


Order #: 1195745

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106


Case #: 703271-9209909



Date Completed:  
before: prep&paint walls



Date Completed:  
before: prep&paint walls 1st floor



Date Completed:  
before: prep&paint walls upstairs



Date Completed:  
before: prep&paint walls upstairs




Account #: 9900158385

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106


Order #: 1195745

Case #: 703271-9209909



Date Completed:

before: prep&paint walls upstairs



Date Completed:

before: prep&paint walls upstairs



Date Completed:

before: provide complete circuit directory



Date Completed:

before: provide complete circuit directory



Account #: 9900158385

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Order #: 1195745

Case #: 703271-9209909




Date Completed:

before: provide complete circuit directory




Date Completed:

before: refinish hardwood floor bedroom



Date Completed:

before: refinish hardwood floor hallway



Date Completed:

before: refinish hardwood floor livingroom



Account #: 9900158385

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Order #: 1195745

Case #: 703271-9209909



Date Completed:

before: refinish hardwood floor livingroom



Date Completed:

before: refinish wood floor closet



Date Completed:

before: refinish wood floor hallway



Date Completed:

before: remove improper wiring in attic



Account #: 9900158385

Order #: 1195745

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Case #: 703271-9209909



Date Completed:

before: remove improper wiring in attic




Date Completed:

before: replace light fixture



Date Completed:

before: repair cracks in ceiling



Date Completed:

before: repair cracks in ceiling




Account #: 9900158385


Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Order #: 1195745


Case #: 703271-9209909




Date Completed:  
before: repair cracks in ceiling



Date Completed:  
before: repair cracks in ceiling



Date Completed:  
before: repair cracks in ceiling



Date Completed:  
before: repair cracks in ceiling



Account #: 9900158385

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Order #: 1146141

Case #: 703271-9209909



Date Completed: 09/03/2012

ac unit



Date Completed: 09/03/2012

address



Date Completed: 09/03/2012

address



Date Completed: 09/03/2012

debris interior-remove 4 cyds of fallen insulation



Account #: 9900158385

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Order #: 1146141

Case #: 703271-9209909



Date Completed: 09/03/2012  
debris interior-remove 4 cyds of fallen insulation



Date Completed: 09/03/2012  
debris interior-remove 4 cyds of fallen insulation



Date Completed: 09/03/2012  
debris interior-remove 4 cyds of fallen insulation



Date Completed: 09/03/2012  
debris interior-remove 4 cyds of fallen insulation



Account #: 9900158385

Order #: 1146141

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Case #: 703271-9209909



Date Completed: 09/03/2012

debris interior-remove 4 cyds of fallen insulation



Date Completed: 09/03/2012

debris interior-remove 4 cyds of fallen insulation



Date Completed: 09/03/2012

debris interior-remove 4 cyds of fallen insulation



Date Completed: 09/03/2012

debris interior-remove 4 cyds of fallen insulation



Account #: 9900158385

Order #: 1146141


Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Case #: 703271-9209909



Date Completed: 09/03/2012

debris interior-remove 4 cyds of fallen insulation



Date Completed: 09/03/2012

debris interior-remove 4 cyds of fallen insulation



Date Completed: 09/03/2012

extermination-exterminate 2 active bee hives using



Date Completed: 09/03/2012

extermination-exterminate 2 active bee hives using



Account #: 9900158385

Order #: 1146141

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Case #: 703271-9209909



Date Completed: 09/03/2012

front of home




Date Completed: 09/03/2012

garage



Date Completed: 09/03/2012

general property



Date Completed: 09/03/2012

general property



Account #: 9900158385

Order #: 1146141

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106


Case #: 703271-9209909



08/30/12 12:49:45 AM

Date Completed: 09/03/2012

general property



08/30/12 12:38:45 AM

Date Completed: 09/03/2012

general property



08/30/12 12:38:52 AM

Date Completed: 09/03/2012

general property



08/30/12 12:39:04 AM

Date Completed: 09/03/2012

general property



Account #: 9900158385

Order #: 1146141

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Case #: 703271-9209909



08/30/12 12:39:06 AM

Date Completed: 09/03/2012

general property



08/30/12 12:37:44 AM

Date Completed: 09/03/2012

general property



08/30/12 12:41:04 AM

Date Completed: 09/03/2012

general property



08/30/12 12:41:11 AM

Date Completed: 09/03/2012

general property




Account #: 9900158385

Order #: 1146141

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Case #: 703271-9209909




Date Completed: 09/03/2012  
general property



Date Completed: 09/03/2012  
general property



Date Completed: 09/03/2012  
general property



Date Completed: 09/03/2012  
general property




Account #: 9900158385


Order #: 1146141

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Case #: 703271-9209909



Date Completed: 09/03/2012  
general property



Date Completed: 09/03/2012  
general property



Date Completed: 09/03/2012  
general property



Date Completed: 09/03/2012  
general property




Account #: 9900158385


Order #: 1146141

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Case #: 703271-9209909




Date Completed: 09/03/2012  
general property



Date Completed: 09/03/2012  
lock box



Date Completed: 09/03/2012  
miscellaneous-cover 3 holes in floor in attic, eac



Date Completed: 09/03/2012  
miscellaneous-cover 3 holes in floor in attic, eac



Account #: 9900158385

Order #: 1146141

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Case #: 703271-9209909



08/30/12 12:47:37 AM

Date Completed: 09/03/2012

miscellaneous-cover 3 holes in floor in attic, eac



08/30/12 12:47:41 AM

Date Completed: 09/03/2012

miscellaneous-cover 3 holes in floor in attic, eac



08/30/12 12:47:45 AM

Date Completed: 09/03/2012

miscellaneous-cover 3 holes in floor in attic, eac



08/30/12 12:39:10 AM

Date Completed: 09/03/2012

miscellaneous-install 2 outlet covers and 1 blank



Account #: 9900158385

Order #: 1146141

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Case #: 703271-9209909



08/30/12 12:39:16 AM

Date Completed: 09/03/2012


miscellaneous-install 2 outlet covers and 1 blank



08/30/12 12:39:35 AM

Date Completed: 09/03/2012

miscellaneous-install 4 3x10 inch floor vents; req



08/30/12 12:39:45 AM

Date Completed: 09/03/2012

miscellaneous-install 4 3x10 inch floor vents; req



08/30/12 12:40:17 AM

Date Completed: 09/03/2012

miscellaneous-install 4 3x10 inch floor vents; req



Account #: 9900158385

Order #: 1146141

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Case #: 703271-9209909



08/30/12 12:51:26 AM

Date Completed: 09/03/2012  
missing elec meter



08/30/12 12:51:29 AM

Date Completed: 09/03/2012  
missing elec meter



08/30/12 12:42:22 AM

Date Completed: 09/03/2012  
mold-bleach and kilz 624 sq ft of mold using 2 gal



08/30/12 12:42:32 AM

Date Completed: 09/03/2012  
mold-bleach and kilz 624 sq ft of mold using 2 gal




Account #: 9900158385

Order #: 1146141

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106


Case #: 703271-9209909



08/30/12 12:42:36 AM

Date Completed: 09/03/2012

mold-bleach and kilz 624 sq ft of mold using 2 gal



08/30/12 12:42:43 AM

Date Completed: 09/03/2012

mold-bleach and kilz 624 sq ft of mold using 2 gal



08/30/12 12:42:58 AM

Date Completed: 09/03/2012

mold-bleach and kilz 624 sq ft of mold using 2 gal



08/30/12 12:37:16 AM

Date Completed: 09/03/2012

ocn lock box




Account #: 9900158385


Order #: 1146141

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Case #: 703271-9209909



Date Completed: 09/03/2012  
posting



Date Completed: 09/03/2012  
rear of home



Date Completed: 09/03/2012  
side of home



Date Completed: 09/03/2012  
side of home








Account #: 9900158385

Order #: 1146141


Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Case #: 703271-9209909



Date Completed: 09/03/2012

toilet



Date Completed: 09/03/2012

warning sticker



Date Completed: 09/03/2012

working keys



Five Brothers

Account #: 9900158385

Order #: 1044707

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Case #: 703271-9209909




Date Completed: 05/04/2012

address



Date Completed: 05/04/2012

front



Date Completed: 05/04/2012

miscellaneous-spray foam in rotting section of tri



Date Completed: 05/04/2012

miscellaneous-spray foam in rotting section of tri




Account #: 9900158385

Order #: 1044707


Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Case #: 703271-9209909




Date Completed: 05/04/2012

miscellaneous-spray foam in rotting section of tri




Date Completed: 05/04/2012

no trip charge -verify no damage



Date Completed: 05/04/2012

no trip charge -verify no damage



Date Completed: 05/04/2012

no trip charge -verify no damage




Account #: 9900158385

Order #: 1044707

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Case #: 703271-9209909




Date Completed: 05/04/2012

no trip charge -verify no damage



Date Completed: 05/04/2012

no trip charge -verify no damage



Date Completed: 05/04/2012

no trip charge -verify no damage



Date Completed: 05/04/2012

no trip charge -verify no damage



Five Brothers

Account #: 9900158385

Order #: 1044707

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Case #: 703271-9209909




Date Completed: 05/04/2012  
no trip charge -verify no damage



Date Completed: 05/04/2012  
no trip charge -verify no damage



Date Completed: 05/04/2012  
no trip charge -verify no damage



Date Completed: 05/04/2012  
no trip charge -verify no damage



Account #: 9900158385

Order #: 1044707

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Case #: 703271-9209909




Date Completed: 05/04/2012

no trip charge -verify no damage




Date Completed: 05/04/2012

no trip charge -verify no damage



Date Completed: 05/04/2012

no trip charge -verify no damage



Date Completed: 05/04/2012

no trip charge -verify no damage



Five Brothers

Account #: 9900158385

Order #: 1044707

Address: 699 & 701 HAWTHORNE AVE E ST PAUL MN 55106

Case #: 703271-9209909




Date Completed: 05/04/2012  
no trip charge -verify no damage



Date Completed: 05/04/2012  
no trip charge -verify no damage



Date Completed: 05/04/2012  
no trip charge -verify no damage



Date Completed: 05/04/2012  
no trip charge -verify no damage