


Date: November 04, 2010
File #: 10 - 918956
Folder Name: 885 CENTRAL AVE W
PIN: 352923310188


HP District:
Property Name:
Survey Info:



Front postings



Rear posting



Rear posting



Garage



Vehicle used for clean-out



North and east sides, postings

Date: November 04, 2010
File #: 10 - 918956
Folder Name: 885 CENTRAL AVE W
PIN: 352923310188

HP District:
Property Name:
Survey Info:



South and east sides, postings



South side, postings



West and south sides

Date: May 15, 2012
File #: 10 - 918956
Folder Name: 885 CENTRAL AVE W
PIN: 352923310188

HP District:
Property Name:
Survey Info:



Missing heating plant



Improper electrical wiring



Unapproved plumbing alteration



South side of house



Roof repairs



Garage

Date: May 15, 2012
File #: 10 - 918956
Folder Name: 885 CENTRAL AVE W
PIN: 352923310188

HP District:
Property Name:
Survey Info:



Deteriorated and missing 2nd floor porch/steps/rails



Rot damaged rear porch



Extension cord wiring to light fixture



Water damaged ceiling



Water damaged flooring



Stairs to basement – no hand rail

Date: May 15, 2012
File #: 10 - 918956
Folder Name: 885 CENTRAL AVE W
PIN: 352923310188


HP District:
Property Name:
Survey Info:



Water damaged and partially collapsed ceiling



Unapproved plumbing alteration



Uncapped gas service



Extension cord wiring to light fixture



Open, altered electrical service



Electric meter

Date: May 15, 2012
File #: 10 - 918956
Folder Name: 885 CENTRAL AVE W
PIN: 352923310188

HP District:
Property Name:
Survey Info:



Open sink drain



Water damaged floor



Water damaged and partially collapsed ceiling



Water damaged ceiling, open chimney



Rodent feces



Open plumbing and gas lines

Date: May 15, 2012
File #: 10 - 918956
Folder Name: 885 CENTRAL AVE W
PIN: 352923310188

HP District:
Property Name:
Survey Info:



Water damaged ceiling



Water damaged floor



Leaking drain



Damaged floor covering



Improper toilet installation



Damaged wall

Date: May 15, 2012
File #: 10 - 918956
Folder Name: 885 CENTRAL AVE W
PIN: 352923310188

HP District:
Property Name:
Survey Info:



Water damaged floor



Mold




Damaged wall



Attic access



Improper hand rail



Improper water heater installation

Date: May 15, 2012
File #: 10 - 918956
Folder Name: 885 CENTRAL AVE W
PIN: 352923310188

HP District:
Property Name:
Survey Info:



Water on dirt floor, improper drain into stack

Date: May 21, 2012
File #: 10 - 918956
Folder Name: 885 CENTRAL AVE W
PIN: 352923310188

HP District:
Property Name:
Survey Info:



Rear posting



Front posting