

# INSPECTION REQUEST

Address: 1724 BEECH ST

Residential       Residential/Commercial       Commercial

Type Construction: One and 1/3 story wood frame

Category: II      Accessory Structures: Detached 1 stall garage

Referred By: Sentinel Field Services Of:

Condemned:    Yes     No     Date:

Dwelling vacant and secure by own means. Roof shingles deteriorated on dwelling and garage, rotting wood on front porch and rear deck, storm window corroded, holes in siding on dwelling and garage, peeling paint on interior windows. Vacant for over a year. Compliant that work was done without permits in 2013. Gas meter valve open.



Category: II

Photos: yes  
Placards: yes

Signed: **Dave Nelmark**

Date: May 12, 2014

