WORK PLAN - BREAKDOWN COST OF REHABILATION
(To be done in accordance with the Code Compliance Inspection Report) **Address:** 1393 Prosperity Avenue, Saint Paul, MN 55106

WEEK OF	TASKS	CONTRACTOR	Supplies/Materials on hand (if any)	Needed Supplies/Materials	Owner/Developer Labor	Value of Cost
1/9/2021	1	Metro heating + Coiling				$150
Completed	2				Previous owner	$0
Completed	3	MN AIR Duct Cleaners		[redacted]		$500
1/9/2021	4	Appliance Co. / Metro heating		New dryer / Washer		$1000 - 1200
Completed	5				Tenant moved	$0
1/9/2021	6	Quick floors LLC		Vinyl Planks		$598
Completed	7	Quick floors LLC				$50
	8	Metro heating + Coiling				$150

Total Project Cost: $ 1750 to 1950

Note: (Code Enforcement Officers estimate the cost to repair this structure is $_____ to $_____).