

Phase 1: Items Completed or N/A

#2 Carbon Monoxide Detectors Installed ^{see photo}

#3 N/A We have a bathroom upstairs that meets said definition ^{see photo}

#4 Just Aaron

#5 Appealing to be grandfathered in

#6 Combustible materials removed

#8 Dryer Venting: It's a ventless dryer (see mechanical code 504.1 regarding condensing dryers)

#10. Have no temporary lighting or extension cords in use.

#11. No exposed wires

#12. Floors are in good condition (may sand & finish at a later time)

#13. Furnace works

#14. It is clean & free of garbage

Phase 1 cont.

- #16. moved furniture so window can be accessed for a fire escape
- #17. There is no mold or mildew present
- #18. Plumbing doesn't leak
- #19. Fridge has been replaced
- #20. Walls are fine (see photos)
- #21. Ceilings are fine (see photos)
- #24. Woodwork is fine (see photos)
- #26. Door in question ^{was removed} storm door used as dog door
- #28. Shed contains a lock
- #29. Scrapping is not nor has not occurred

Phase 2:

7. Will Reorganize Storage in
the basement & the upstairs
by January 15th

15 will be ensured when
above matter (#7) is completed
by January 15th

22 Storage : see above #s
7 & 15

Phase 3 Items that are weather dependent and will be done in spring.

#9. Eaves / soffits

#25. Pouring cement must wait

#27 Exterior walls

#23 Crack in window - will glaze & replace glass when weather better

#28 Garage Door to be replaced in spring