

We need the following to process your appeal:

(if cash: receipt number

APPLICATION FOR APPEAL

Saint Paul City Council – Legislative Hearings

DEC 15 2016

CITY CLERK

\$25 filing fee (non-refundable) (payable to the City of Saint Paul) HEARING DATE & TIME

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8585

Revised 8/11/2014

(provided by Legislative Hearing Office)

Copy of the City-issued orders/letter being appealed Attachments you may wish to include This appeal form completed	Tuesday, Dec. 20
	Location of Hearing:
₩ Walk-In OR □ Mail-In	Room 330 City Hall/Courthouse
for abatement orders only: Email OR Fax	
Address Being Appealed:	
Number & Street: 242 Congress St E City: Saint Paul State: MN Zip: 55107	
Appellant/Applicant: Mackonnen Hidru Email M. Hidru & Yahoo.com	
Phone Numbers: Business Residence 612-20	67-6616 Cell 612-267-6616
Signature: Mackern Hi'Lu	Date:
Name of Owner (if other than Appellant):	
Mailing Address if Not Appellant's: 133 64 Fordham Ave, Apple Valley, MN 55124	
Phone Numbers: Business Residence	Cell
What Is Being Appealed and Why? Attachments Are Acceptable Vacate Order/Condemnation/ Revocation of Fire C of O	
□ Summary/Vehicle Abatement	
□ Fire C of O Deficiency List/Correction	
Code Enforcement Correction Notice More file	e.
□ Vacant Building Registration	
Other (Fence Variance, Code Compliance, etc.)	



CITY OF SAINT PAUL

Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Telephone: 651-266-8989 Saint Paul, MN 55101-1806 Fax: 651-266-8951

December 13, 2016

MACKONNEN HIDRU 13364 FORDHAM AVE APPLE VALLEY MN 55124 USA

CORRECTION NOTICE - COMPLAINT INSPECTION

RE:

242 CONGRESS ST E

Ref. # 14787

Dear Property Representative:

An inspection was made of your building on December 13, 2016 in response to a referral. You are hereby notified that the following deficiency list must be corrected immediately.

A re-inspection will be made on December 16, 2016 at 1:00pm. Failure to comply will result in enforcement action.

Failure to comply may result in a criminal citation or revocation of the Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Certificate of Occupancy. The code also provides for the assessment of additional re-inspection fees.

DEFICIENCY LIST

- 1. Building Throughout Minimum Heat SPLC 34.11 (6) Provide and maintain a minimum of 68 degrees F in all habitable rooms at all times.-Provide and maintain a minimum of 68 degrees F in all habitable areas measured at 5 feet off the floor at all times.
- 2. Main Floor Exterior Doors SPLC 34.33 (3) Repair and maintain the door in good condition.Provide approved weather-stripping around all door frames on the doors leading to the
 exterior.
- 3. Main Floor Red Tagged Gas Range SPLC 34.12 (2), SPLC 34.36 (1) Repair and maintain all required and supplied equipment in an operative and safe condition to properly and safely perform their intended function in accordance with the provisions of the applicable code.
 Repair/replace the gas range that has been red tagged by Xcel Energy as being hazardous.

 The option to remove this gas range is available because there is another gas range installed that is currently functional. If the gas range is removed the gas lines must be capped in an approved manner.

- 4. Main Floor Thermostat SPLC 34.12 (2), SPLC 34.36 (1) Repair and maintain all required and supplied equipment in an operative and safe condition to properly and safely perform their intended function in accordance with the provisions of the applicable code.-Replace the broken/inoperable thermostat.
- 5. Main Floor and Upper Floor Bedrooms Carbon Monoxide Alarms MN State Statute 299F.50 Immediately provide and maintain an approved Carbon Monoxide Alarm in a location within ten (10) feet of each sleeping area. Installation shall be in accordance with manufacturer's instructions.
- 6. Main Floor and Upper Floor Throughout Smoke Alarms MN Stat. 299F.362 Immediately provide and maintain a smoke alarm located outside each sleeping area.-Replace the missing hard-wired smoke alarm in the main floor south bedroom. Replace the inoperable smoke alarm in the upper floor bedroom. Replace all missing batteries in all smoke alarms.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo.

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8585) and must be filed within 10 days of the date of the original orders.

If you have any questions, email me at: wayne.spiering@ci.stpaul.mn.us or call me at 651-266-8993 between 7:30 a.m. - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Wayne Spiering Fire Inspector

Ref. # 14787