Date: July 13, 2011
File #: 10 - 922778
Folder Name: 627 OHIO ST
PIN: 072822240146



North and west face of the west side dormer, missing flashing, water damage siding

Date: July 13, 2011
File #: 10 - 922778
Folder Name: 627 OHIO ST
PIN: 072822240146



Unapproved exterior electrical wiring

July 13, 2011 10 - 922778 Date: File #: Folder Name: **627 OHIO ST** PIN: 072822240146



Water damaged ceiling, peeling paint, possibly mold

Date: July 13, 2011 File #: 10 - 922778 Folder Name: 627 OHIO ST PIN: 072822240146



South and west face of the west side dormer, missing flashing, water damaged siding