

□ Other

APPLICATION FOR APPEAL

PECEIVED

JAN 1 4 2011

CITY CLERK

Saint Paul City Clerk

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8560

\$25 filing fee payable to the City of Saint Paul (if cash: receipt number) Copy of the City-issued orders or letter which are being appealed Attachments you may wish to include This appeal form completed	YOUR HEARING Date and Time: Tuesday, 1-35-11 Time 1:30 Location of Hearing: Room 330 City Hall/Courthouse
Address Being Appealed:	
Number & Street: 913-925 Kennard City:	St. Paul State: MN Zip: 55/06
Appellant/Applicant: Leng (am)	Email YangozII @ METNET
Phone Numbers: Business 51-442-340 Residence	\mathcal{J}
Name of Owner (if other than Appellant):	
Name of Owner (if other than Appellant):	g Yang
Address (if not Appellant's):	
Phone Numbers: Business Residence	Cell
What Is Being appealed and why?	Attachments Are Acceptable
Vacate Order/Condemnation/ Revocation of Fire C of O	
□ Summary/Vehicle Abatement	
□ Fire C of O Deficiency List	
Fire C of O: Only Egress Windows	
Code Enforcement Correction Notice	
□ Vacant Building Registration	*
□ Other	
□ Other	



CITY OF SAINT PAUL Christopher B. Coleman, Mayor 375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806 Telephone: 651-266-8989 Facsimile: 651-266-8951 Web: www.stpaul.gov/dsi

January 7, 2011

LENG YANG 1151 SOUTH TRAPPERS CROSSING LINO LAKES MN 55038-9138

FIRE INSPECTION CORRECTION NOTICE

RE:

923 KENNARD ST

Ref. #105986

Residential Class: C

Dear Property Representative:

Your building was inspected on January 7, 2011 for the renewal of your Fire Certificate of Occupancy. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected prior to the re-inspection date. A re-inspection will be made on January 27, 2011 at 1:00 P.M..

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional re-inspection fees.

YOU WILL BE RESPONSIBLE FOR NOTIFYING TENANTS IF ANY OF THE FOLLOWING LIST OF DEFICIENCIES ARE THEIR RESPONSIBILITY.

DEFICIENCY LIST

- 1. 923 SPLC 34.10 (4), 34.33 (3) Provide a bathroom floor impervious to water. After securing to the toilet caulk the base.
- 2. 923 SPLC 34.11, SBC 2902.1, SPLC 34.17, MPC 415.0220 Repair or replace and maintain the plumbing fixture to an operational condition.-Repair or replace and maintain an approved private toilet. Secure toilet to floor
- 3. 923 and 925 MN State Statute 299F.50 Immediately provide and maintain an approved Carbon Monoxide Alarm in a location within ten (10) feet of each sleeping area. Installation shall be in accordance with manufacturers instructions.
- 4. 925 MSFC 605.1 Remove unapproved exposed wiring and install in accordance with the electrical code. This work may require a permit(s). Call DSI at (651) 266-9090.-KITCHEN ABOVE STOVE
- 5. 925 SPLC 34.10 (7), 34.33 (6) Repair and maintain the walls in an approved manner. Remove all mold from all walls-Repair or replace the damaged or deteriorated wall coverings.

An Equal Opportunity Employer

- 6. 925 SPLC 34.10 (7), 34.33 (6) Repair and maintain the ceiling in an approved manner.-Repair or replace the damaged or deteriorated ceiling. Paint the ceiling. Patch the holes and/or cracks in the ceiling.
- 7. 925 MSFC 605.6 Provide electrical cover plates to all outlets, switches and junction boxes where missing.-You have a broken cover plate in living room
- 8. 925 and 923 All Bedrooms windows MSFC1026.1 Provide and maintain an approved escape window from each sleeping room. The minimum size must be 5 square feet of glazed area with a minimum of 24 inches of openable height and 20 inches of openable width. With a finished sill height not more than 48 inches. This work may require permit(s). Call DSI at (651)- 266-9090. Refer to the Escape Windows for Residential Occupancies handout for more information.- Measured 21inches openable height and 39inches openable width Glazed 38inches height by 35inches width These are double hung windows.
- 9. SPLC 34.09 (1) b,c, 34.32 (1) b,c Provide and maintain all exterior walls free from holes and deterioration. The south side of the building has siding that has been blown away or removed and is hanging by a piece of material. Repair immediately.
- 10. SPLC 34.11 (6), 34.34 (3) Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.
- 11. SPLC 39.02(c) Complete and sign the provided smoke detector affidavit and return it to this office.
- 12. SPLC 34.09 (1) e, 34.32 (1) d Provide and maintained the roof weather tight and free from defects.

For an explanation or information on some of the violations contained in this report, please visit our web page at: http://www.ci.stpaul.mn.us/index.aspx?NID=211

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8688) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: james:thomas@ci.stpaul.mn.us or call me at 651-266-8983 between 7:30 a.m. - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

James Thomas Fire Inspector

Reference Number 105986