## Historic Sites Survey Ramsey County Historical Society Saint Paul Heritage Preservation Commission

	Ramsey County Historical Society Saint Taur Heritage Trescreation Commission	
1.	Street Address/ Location: 718 W. Watson Avenue	
2	District/village: 9 3. Common name:	
4	Historic name: 5. Original use: House	
6.	Present Use: House 7. Access: Yes X No Limited	
	Period of construction: ca. 1875 9. Style: Mildly Italianate	
	# of bays: 2 11. # of stories: 1½ 12. Roof style: Intersecting gable	
	Roof covering: hexagonal shingles 14. Dormer style & #: none	
	Chimney style, material, location & #: 1 new interior brick	
	Type of fenestration: 1/1, 2/2 rectangular	
	Type of foundation: limestone	
18.	Structural system/main exterior wall covering: X Wood frame:clapboardshing	jle
	aluminumXasbestosBrick:stretcher bondAmerican bondheader bond	
	Stone:random rubblecoursed rubblerandom ashlarcoursed ashlar	
	Type of stone/brick or other bonding pattern:	
	Concrete blockCast concreteStuccoTerra cottaCurtain wall	
	Glass/metal Other:	
19.	Other significant details: This picturesque cottage features an ornate porch with turned columns and brackets. The porch roof extends around a bay window. Transom window over door. Transom over window on right facade. Attic level window on main facade has pedimented window ho enframing slightly segmental arched opening. Attic window on side of house is point arched.	er ood
20.	Integrity of Design:basically intact & unaltered _Xaltered slightly	
	alterations & additions more apparent than originaloriginal design not apparent	cent
21.	Physical condition of building:ExcellentGood _XFairPoorDeteriorate	ed
22.	Additions and alterations: Several rear additions, siding.	
2.2	TS - segment lot describe. NW NE SE SW corner of	
	. If a corner lot, describe: NW NE SE SW corner of cross street	
	Setting:acricultural _Xresidentialcommercialindustrialsuburban	
23.	Other:	
26.	Significant site and landscape features: Low limestone retaining wall.	
27.	. Threats to site:	
28.	. Additional comments:	
20	. Date(s) of site visit(s): 6/19/81	
	Negative file number(s): 53/9/8	
	Map location code(if applicable):	
	Name of fieldworker: P. Murphy	
34.	. Name of frequencial: f. Mulphy	